

4 SUNSET DR APT 1	N/A	N	N	U	U	Visual Inspection/Survey Response	C	C	C	NL		N/R	N			N	
2 SUNSET DR APT 1	N/A	N	N	U	U	Visual Inspection/Survey Response	C	C	C	NL		N/R	N			N	
2 SUNSET DR APT 2	N/A	N	N	U	U	Visual Inspection/Survey Response	C	C	C	NL		N/R	N			N	
2 SUNSET DR APT 3	N/A	N	N	U	U	Visual Inspection/Survey Response	C	C	C	NL		N/R	N			N	
2 SUNSET DR APT 4	N/A	N	N	U	U	Visual Inspection/Survey Response	C	C	C	NL		N/R	N			N	
5 SUNSET DR APT A	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
5 SUNSET DR APT B	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
5 SUNSET DR APT C	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
5 SUNSET DR APT D	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
5 SUNSET DR APT E	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
5 SUNSET DR APT F	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
5 SUNSET DR APT G	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
5 SUNSET DR APT H	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
1005 W APPLE ST	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
5420 WILLOW SPRINGS LN	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
5490 WILLOW SPRINGS LANE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
5535 WILLOW SPRINGS LN	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
1041 W APPLE ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
1057 W APPLE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
1208 W APPLE ST	N/A	N	N	U	U	Construction Records	P	P	P	NL		N/R	N			N	
109 S WEST ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
107 S WEST ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
105 S WEST ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
101 S WEST ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
2 CHERRY TREE LN	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
3 CHERRY TREE LN	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
4 CHERRY TREE LN	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
6 CHERRY TREE LN	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
606 W HIGH ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
604 W HIGH ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
602 W HIGH ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
8 S POTTER ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
6 S POTTER ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
2 S POTTER ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
1 N POTTER ST	N/A	N	N	U	U	Visual Inspection/Survey Response	C	C	C	NL		N/R	N			N	
1 A N POTTER ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
3 N POTTER ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
5 N POTTER ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
6 N POTTER ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
4 N POTTER ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
2 N POTTER ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
1 S POTTER ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
3 S POTTER ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
504 W HIGH ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
505 W HIGH ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
601 W HIGH ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
2 N WEST ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
9 N WEST ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
7 N WEST ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
3 N WEST ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
4 N WEST ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
1 N WEST ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
1 S WEST ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
701 KESSLER RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
102 WESTVIEW DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
104 WESTVIEW DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
108 WESTVIEW DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
110 WESTVIEW DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
112 WESTVIEW DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
114 WESTVIEW DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
118 WESTVIEW DR	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
120 WESTVIEW DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
906 WOLF RD	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
1244 WOLF RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
1238 WOLF RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
1230 WOLF ROAD	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	

1220 WOLF RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
1207 WOLF RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
1201 WOLF RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
1203 WOLF RD	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
601 NIEBRUEGGE LN	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
1209 WOLF RD	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
600 NIEBRUEGGE LN	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
651 NIEBRUEGGE LN	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
650 NIEBRUEGGE LN	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
701 NIEBRUEGGE LN	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
700 NIEBRUEGGE LN	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
711 NIEBRUEGGE LN	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
750 NIEBRUEGGE LN	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
751 NIEBRUEGGE LN	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
801 NIEBRUEGGE LN	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
811 NIEBRUEGGE LN	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
851 NIEBRUEGGE LN	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
901 NIEBRUEGGE LN	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
850 CABIN CREEK	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
860 CABIN CREEK	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
1001 NIEBRUEGGE LN	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
1000 NIEBRUEGGE LN	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
1140 NIEBRUEGGE LANE	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
1150 NIEBRUEGGE LN	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
1248 WOLF RD	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
800 NIEBRUEGGE LN	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
1252 WOLF RD	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
1225 WOLF RD	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
1237 WOLF RD	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
1241 WOLF RD	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
1256 WOLF RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
1266 WOLF RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
1272 WOLF RD	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
1278 WOLF RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
1302 WOLF RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
1312 WOLF RD	N/A	N	N	U	U	Visual Inspection/Survey Response	C	C	C	NL		N/R	N			N	
1320 WOLF RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
1328 WOLF RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
1336 WOLF RD	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
5818 COUNTRYSIDE LN	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
5822 COUNTRYSIDE LN	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
5826 COUNTRYSIDE LN	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
5920 COUNTRYSIDE LN	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
5938 COUNTRYSIDE LN	N/A	N	N	U	U	Visual Inspection	P	P	C	NL		N/R	N			N	
3790 SUGAR LAKE DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
3770 SUGAR LAKE DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
3750 SUGAR LAKE DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
3730 SUGAR LAKE DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
3700 SUGAR LAKE DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
3550 SUGAR LAKE DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
3500 SUGAR LAKE DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
3270 SUGAR LAKE DR	N/A	N	N	U	U	Survey Response/Logbook/Visual Inspection	P	P	P	NL		N/R	N			N	
3250 SUGAR LAKE DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
3200 SUGAR LAKE DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
3201 SUGAR LAKE DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
3251 SUGAR LAKE DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
3271 SUGAR LAKE DR	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
3291 SUGAR LAKE DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
1202 ANISE CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
1200 ANISE CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
3501 SUGAR LAKE DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	

3551 SUGAR LAKE DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
1204 CINNAMON DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
1201 CINNAMON DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
1202 CINNAMON DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
1203 CINNAMON DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
1200 CINNAMON DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
1205 CINNAMON DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
5939 COUNTRYSIDE LN	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
3701 SUGAR LAKE DR	N/A	N	N	U	U	Visual Inspection/Survey Response	C	C	C	NL		N/R	N			N	
3731 SUGAR LAKE DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
3751 SUGAR LAKE DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
3771 SUGAR LAKE DR	N/A	N	N	U	U	Material Invoice/Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
5945 COUNTRYSIDE LN	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
5955 COUNTRYSIDE LN	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
5963 COUNTRYSIDE LN	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
6201 COUNTRYSIDE LN	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
6205 COUNTRYSIDE LN	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
6668 SCHIERMEIER RD	N/A	N	N	U	U	Visual Inspection	P	p	C	NL		N/R	N			N	
6343 COUNTRYSIDE LN	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
6355 COUNTRYSIDE LN	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
6363 COUNTRYSIDE LN	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
6367 COUNTRYSIDE LN	N/A	N	N	U	U	Visual Inspection/Survey Response	C	C	P	NL		N/R	N			N	
102 CEDAR LANE	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
104 CEDAR LANE	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
106 CEDAR LANE	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
202 CEDAR LANE	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
206 CEDAR LANE	LC4T031	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
210 CEDAR LANE	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
302 CEDAR LANE	N/A	N	N	U	U	Construction Records	C	C	P	NL		N/R	N			N	
310 CEDAR LANE	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
10 SPRUCE DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
9 SPRUCE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
8 SPRUCE DR	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
7 SPRUCE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
6 SPRUCE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
4 SPRUCE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
3 SPRUCE DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
10 WESTBROOK LANE	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
9 WESTBROOK LANE	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
8 WESTBROOK LANE	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
7 WESTBROOK LANE	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
6 WESTBROOK LANE	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
5 WESTBROOK LANE	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
4 WESTBROOK LANE	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
3 WESTBROOK LANE	LC4T043	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
2 WESTBROOK LANE	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
1 SPRUCE DR	LC4T044	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
311 CEDAR LANE	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
707 PINE TREE LANE	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
709 PINE TREE LANE	LC4T028	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
711 PINE TREE LANE	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
713 PINE TREE LANE	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
715 PINE TREE LANE	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
305 PINE TREE LANE	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
207 PINE TREE LANE	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
712 PINE TREE LANE	LC4T029	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
710 PINE TREE LANE	LC4T041	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
708 PINE TREE LANE	LC4T042	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
209 CEDAR LANE	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
207 CEDAR LANE	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
204 PINE TREE LANE	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
205 PINE TREE LANE	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
203 PINE TREE LANE	LC5T036	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
201 PINE TREE LANE	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
103 PINE TREE LANE	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
101 PINE TREE LANE	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
711 KESSLER RD	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
710 KESSLER RD	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	

706 KESSLER RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
708 KESSLER RD	N/A	N	N	U	U	Survey Response	C	C	C	NL	N/R	N	N
101 N WEST ST	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N
105 N WEST ST	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N
107 N WEST ST	N/A	N	N	U	U	Survey Response	C	C	P	NL	N/R	N	N
203 N WEST ST	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N
207 N WEST ST	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N
412 N WEST ST	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N
610 W MILL ST	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N
210 N WEST ST	LCAT030	N	N	U	U	Survey Response	C	C	C	NL	N/R	N	N
310 N WEST ST	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N
610 W PHILLIPS ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
110 N WEST ST	N/A	N	N	U	U	Survey Response	C	C	C	NL	N/R	N	N
106 N WEST ST	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N
612 W ST CLAIR ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
101 N POTTER ST	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL	N/R	N	N
102 N POTTER ST	N/A	N	N	U	U	Survey Response	C	C	C	NL	N/R	N	N
105 N POTTER ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
606 W PHILLIPS ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
602 W PHILLIPS ST	N/A	N	N	U	U	Survey Response	C	C	C	NL	N/R	N	N
205 N POTTER ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
211 N POTTER ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
600 W MILL ST	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N
300 N POTTER ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
507 W MILL ST	N/A	N	N	U	U	Survey Response	C	C	P	NL	N/R	N	N
212 N POTTER ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
204 N POTTER ST	N/A	N	N	U	U	Survey Response	C	C	C	NL	N/R	N	N
202 N POTTER ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
111 N WALNUT ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
570 W PHILLIPS ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
205 N WALNUT ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
207 N WALNUT ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
204 N WALNUT ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
210 N WALNUT ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
208 N WALNUT ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
211 N WALNUT ST	LCS7035	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
512 W TEMPLE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL	N/R	N	N
560 W PHILLIPS ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
108 N WALNUT ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
106 N WALNUT ST	N/A	N	N	U	U	Survey Response	C	C	P	NL	N/R	N	N
104 N WALNUT ST	N/A	N	N	U	U	Survey Response	C	C	C	NL	N/R	N	N
102 N WALNUT ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
408 W ST CLAIR ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
506 W ST CLAIR ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
6 N WALNUT ST	N/A	N	N	U	U	Survey Response	C	C	P	NL	N/R	N	N
5 N WALNUT ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
3 N WALNUT ST	N/A	N	N	U	U	Visual Inspection	C	C	P	NL	N/R	N	N
3 HARRIS CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
5 HARRIS CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
7 HARRIS CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
9 HARRIS CT	N/A	N	N	U	U	Survey Response	C	C	P	NL	N/R	N	N
11 HARRIS CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
13 HARRIS CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
15 HARRIS CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
16 HARRIS CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
14 HARRIS CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
12 HARRIS CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
10 HARRIS CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
8 HARRIS CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
6 HARRIS CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
4 HARRIS CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
2 HARRIS CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
2 S WALNUT ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
1 CARDINAL CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
3 CARDINAL CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
5 CARDINAL CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
7 CARDINAL CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
9 CARDINAL CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
11 CARDINAL CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
111 S WALNUT ST	N/A	N	N	U	U	Survey Response	C	C	C	NL	N/R	N	N

12 S WALNUT ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
202 S WALNUT ST	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
204 S WALNUT ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
208 S WALNUT ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
520 W APPLE ST	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
211 S WALNUT ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
205 S WALNUT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
502 W APPLE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
203 S WALNUT ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
201 S WALNUT ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
412 W HIGH ST	N/A	N	N	U	U	Visual Inspection	O	O	O	NL		N/R	N			N	
412 W HIGH ST	N/A	N	N	U	U	Visual Inspection	O	O	O	NL		N/R	N			N	
2 S RAILROAD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
407 W HIGH ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
502 W WHITE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
8 N RAILROAD ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
10 N RAILROAD ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
7 N MAIN ST	N/A	N	N	U	U	Visual Inspection/Visual Inspection/Survey Response	C	C	C	NL		N/R	N			N	
9 N MAIN ST	N/A	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C	NL		N/R	N			N	
15 N MAIN ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
507 W ST CLAIR	LC3T026	N	N	U	U	Visual Inspection	C	C	GRR	GRR	Y	N/R	N			N	
508 W ST CLAIR ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
105 N MAIN ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
107 N MAIN ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
111 N MAIN ST	LC3T019	N	N	U	U	Visual Inspection	C	C	GRR	GRR	Y	N/R	N			N	
202 N RAILROAD ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
204 N RAILROAD ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
208 N RAILROAD ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
210 N RAILROAD ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
212 N RAILROAD ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
201 N MAIN ST	N/A	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C	NL		N/R	N			N	
205 N MAIN ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
209 N MAIN ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
302 N RAILROAD ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
304 N RAILROAD ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
306 N RAILROAD ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
308 N RAILROAD ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
310 N RAILROAD ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
312 N RAILROAD ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
301 N MAIN ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
303 N MAIN ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
311 N MAIN ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
412 W TEMPLE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
406 N RAILROAD	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
408 N RAILROAD ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
412 N RAILROAD ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
401 N MAIN ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
407 N MAIN ST	LC3T002	N	N	U	U	Survey Response	C	C	GRR	GRR	Y	N/R	N			N	
509 N MAIN ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
511 N MAIN ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
513 N MAIN ST	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
515 N MAIN ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
518 N MAIN ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
601 N MAIN ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
603 N MAIN ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
607 N MAIN ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
609 N MAIN ST	N/A	N	N	U	U	Construction Records	C	C	P	NL		N/R	N			N	
613 N MAIN ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
615 N MAIN ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
619 N MAIN ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
621 N MAIN ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
606 N MAIN ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
600 N MAIN ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
516 N MAIN ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
514 N MAIN ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
512 N MAIN ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
510 N MAIN ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
506 N MAIN ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
502 N MAIN ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
500 N MAIN ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
412 N MAIN ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	

408 N MAIN ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
406 N MAIN ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
402 N MAIN ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	Y	2/29/2024	C		N
310 N MAIN ST	LC5T039	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
306 N MAIN ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
302 N MAIN ST	LC5T034	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
214 N MAIN ST	LC4T027	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
210 N MAIN ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
206 N MAIN ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
204 N MAIN ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
312 W PHILLIPS ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
308 W PHILLIPS ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
309 W PHILLIPS ST	N/A	N	N	U	U	Visual Inspection/Visual Inspection	C	C	P	NL		N/R	N			N	
311 W PHILLIPS APT A	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
311 W PHILLIPS ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
114 N MAIN ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
112 N MAIN ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
110 N MAIN ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
106 N MAIN ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
11 N RICHLAND ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
7 N RICHLAND ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
5 N RICHLAND ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
3 N RICHLAND ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
2 S RICHLAND APT 2	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
2 S RICHLAND APT 1	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
2 S RICHLAND	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
10 S RICHLAND ST	N/A	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C	NL		N/R	N			N	
12 S RICHLAND ST	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
102 S RICHLAND ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
106 S RICHLAND ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
108 S RICHLAND ST	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
110 S RICHLAND ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
400 W WASHINGTON ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
407 W WASHINGTON ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
409 W WASHINGTON APT A	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
409 W WASHINGTON APT B	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
409 W WASHINGTON APT C	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
409 W WASHINGTON APT D	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
409 W WASHINGTON APT E	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
409 W WASHINGTON APT F	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
409 W WASHINGTON APT G	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
409 W WASHINGTON APT H	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
401 W WASHINGTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
206 S RICHLAND ST	N/A	Y	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
308 W APPLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
203 S RICHLAND ST	N/A	Y	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
309 W WASHINGTON ST	N/A	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C	NL		N/R	N			N	
312 W WASHINGTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
107 S RICHLAND ST	N/A	N	N	U	U	Visual Inspection	P	P	P	NL		N/R	N			N	
109 S RICHLAND ST	N/A	N	N	U	U	Visual Inspection	P	P	P	NL		N/R	N			N	
11 S RICHLAND ST	LC3T003	N	N	U	U	Visual Inspection	C	C	GRR	GRR	Y	N/R	N			N	
9 S RICHLAND ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
7 S RICHLAND ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
6 S RICHLAND ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
8 S RICHLAND ST	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
1 S RICHLAND ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
312 W WHITE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
6 N RICHLAND ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
10 N RICHLAND ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
807 N STATE ST	N/A	N	N	U	U	Visual Inspection	P	P	C	NL		N/R	N			N	
697 N STATE STREET	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
701 N STATE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
703 N STATE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
705 N STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
711 N STATE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
708 ROGERS DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
710 ROGERS DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
712 ROGERS DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
707 ROGERS DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
709 ROGERS DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
713 ROGERS DR	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
711 ROGERS DR	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	

911 DEER TRAIL CT	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N		N	
909 DEER TRAIL CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N		N	
906 DEER TRAIL CT	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N		N	
908 DEER TRAIL CT	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N		N	
910 DEER TRAIL CT	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N		N	
306 E MEADOW BROOK DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N		N	
302 E MEADOW BROOK DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N		N	
909 LAKE TRAIL CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N		N	
906 LAKE TRAIL CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N		N	
912 MEADOW BROOK DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N		N	
906 MEADOW BROOK DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N		N	
902 MEADOW BROOK DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N		N	
312 LAKE POINTE CT	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N		N	
308 LAKE POINTE CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N		N	
304 LAKE POINTE CT	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N		N	
300 LAKE POINTE CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N		N	
612 N STATE ST	N/A	Y	N	U	U		C	C	C	NL		N/R	N		N	
620 N STATE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N		N	
705 MEADOW BROOK DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N		N	
707 MEADOW BROOK DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N		N	
709 MEADOW BROOK DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N		N	
713 MEADOW BROOK DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N		N	
717 MEADOW BROOK DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N		N	
721 MEADOW BROOK DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N		N	
725 MEADOW BROOK DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N		N	
803 MEADOW BROOK DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N		N	
301 DOGWOOD CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N		N	
722 MEADOW BROOK DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N		N	
718 MEADOW BROOK DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N		N	
714 MEADOW BROOK DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N		N	
710 MEADOW BROOK DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N		N	
706 MEADOW BROOK DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N		N	
708 MEADOW BROOK DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N		N	
701 OAK BROOK DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N		N	
703 OAK BROOK DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N		N	
705 OAK BROOK DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N		N	
711 OAK BROOK DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N		N	
715 OAK BROOK DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N		N	
719 OAK BROOK DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N		N	
723 OAK BROOK DR	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N		N	
305 DOGWOOD CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N		N	
309 DOGWOOD CT	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N		N	
313 DOGWOOD CT	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N		N	
317 DOGWOOD CT	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N		N	
316 DOGWOOD CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N		N	
720 OAK BROOK DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N		N	
716 OAK BROOK DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N		N	
712 OAK BROOK DR	N/A	N	N	U	U	Visual Inspection/Survey Response	C	C	C	NL		N/R	N		N	
708 OAK BROOK DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N		N	
618 RED OAK DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N		N	
614 RED OAK DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N		N	
610 RED OAK DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N		N	
606 RED OAK DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N		N	
602 RED OAK DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N		N	
603 BROOK STONE CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N		N	
607 BROOK STONE CT	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N		N	
611 BROOK STONE CT	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N		N	
615 BROOK STONE CT	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N		N	
619 BROOK STONE CT	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N		N	
623 BROOK STONE CT	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N		N	
627 BROOK STONE CT	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N		N	
624 BROOK STONE CT	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N		N	

620 BROOK STONE CT	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
612 BROOK STONE CT	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
608 BROOK STONE CT	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
604 BROOK STONE CT	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
600 BROOK STONE CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
346 MEADOW RIDGE DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
348 MEADOW RIDGE DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
356 MEADOW RIDGE DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
601 MEADOW LAKE DR	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
605 MEADOW LAKE DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
607 MEADOW LAKE DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
613 MEADOW LAKE DR	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
617 MEADOW LAKE DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
621 MEADOW LAKE DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
625 MEADOW LAKE DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
629 MEADOW LAKE DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
630 MEADOW LAKE DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
628 MEADOW LAKE DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
624 MEADOW LAKE DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
618 MEADOW LAKE DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
610 MEADOW LAKE DR	N/A	N	N	U	U	Visual Inspection/Survey Response	C	C	P	NL		N/R	N			N	
409 ROSA LN	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
604 N STATE ST	N/A	N	N	U	U	Survey Response	P	P	P	NL		N/R	N			N	
517 N STATE ST	N/A	N	N	U	U	Visual Inspection	P	P	P	NL		N/R	N			N	
519 N STATE ST	N/A	N	N	U	U	Survey Response	P	P	C	NL		N/R	N			N	
212 S MONROE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
301 W WASHINGTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
302 W WASHINGTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
106 S MONROE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
102 S MONROE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
14 S MONROE ST	N/A	Y	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
10 S MONROE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
6 S MONROE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
1 N MONROE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
9 N MONROE ST	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
11 N MONROE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
308 W ST CLAIR ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
302 W ST CLAIR ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
301 W PHILLIPS ST	LC3T004	N	N	U	U	Visual Inspection	C	C	GRR	GRR	Y	N/R	N			N	
305 W PHILLIPS ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
203 N MONROE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
301 W MILL ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
207 N MONROE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
305 W MILL ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
301 N DEWEY ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
305 N DEWEY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
309 N DEWEY ST	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
401 N DEWEY ST	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
411 N DEWEY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
501 N DEWEY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
503 N DEWEY ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
506 N DEWEY ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
508 N DEWEY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
204 W KOESTERER ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
412 N DEWEY ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
406 N DEWEY ST	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
312 W TEMPLE	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
310 N DEWEY ST	LC4T046	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
306 N DEWEY ST	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
302 N DEWEY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
210 N MONROE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
208 N MONROE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
206 N MONROE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
202 N MONROE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
114 N MONROE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
110 N MONROE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
104 N MONROE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	

212 W ST CLAIR ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
12 N MONROE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
8 N MONROE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
209 W HIGH ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
311 W HIGH ST	N/A	N	N	U	U	Visual Inspection	P	P	P	NL		N/R	N			N	
313 W HIGH ST	N/A	N	N	U	U	Visual Inspection	P	P	P	NL		N/R	N			N	
105 S MONROE ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
107 S MONROE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
111 S MONROE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
201 S MONROE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
208 W APPLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
206 W APPLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
212 S BELLEVILLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
201 W WASHINGTON ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
110 S BELLEVILLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
112 S BELLEVILLE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
108 S BELLEVILLE ST	LC3T005	N	N	U	U	Visual Inspection	C	C	GRR	GRR	Y	N/R	N			N	
106 S BELLEVILLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
201 A W HIGH ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
201 B W HIGH ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
102 A S BELLEVILLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
102 B S BELLEVILLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
205 W HIGH ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
109 N BELLEVILLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
203 N BELLEVILLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
205 N BELLEVILLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
211 N BELLEVILLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
201 W MILL ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
202 W MILL ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
305 N MONROE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
309 N MONROE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
401 N MONROE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
407 N MONROE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
411 N MONROE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
501 N MONROE ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
505 N MONROE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
511 N MONROE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
410 N MONROE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
406 N MONROE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
404 N MONROE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
402 N MONROE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
208 W TEMPLE ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
312 N MONROE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
310 N MONROE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
308 N MONROE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
306 N MONROE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
302 N MONROE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
210 N BELLEVILLE ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
208 N BELLEVILLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
206 N BELLEVILLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
112 W PHILLIPS ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
111 W PHILLIPS ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
108 N BELLEVILLE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
106 N BELLEVILLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
112 W ST CLAIR ST	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
8 N BELLEVILLE ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
2 N BELLEVILLE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
1 S BELLEVILLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
9 S BELLEVILLE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
13 S BELLEVILLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
101 S BELLEVILLE ST	N/A	N	N	U	U	Logbook	C	C	C	NL		N/R	Y	2018	C	N	
105 S BELLEVILLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
107 S BELLEVILLE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
110 W WASHINGTON ST	LC5T037	N	N	U	U	Visual Inspection	P	P	P	NL		N/R	N			N	
105 W WASHINGTON ST	N/A	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C	NL		N/R	N			N	
111 W WASHINGTON ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
111 A W WASHINGTON ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
112 W APPLE ST	N/A	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C	NL		N/R	N			N	
108 W APPLE ST	N/A	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C	NL		N/R	N			N	
305 S BELLEVILLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
307 S BELLEVILLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
309 S BELLEVILLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	

311 S BELLEVILLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
313 S BELLEVILLE ST	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N
315 S BELLEVILLE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
308 S ALTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
11 W APPLE ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
101 W APPLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
103 W APPLE ST	LC3T006	N	N	U	U	Survey Response	C	C	GRR	GRR	Y	N/R	N			N
106 W APPLE ST	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N
102 W APPLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
101 W WASHINGTON ST	N/A	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C	NL		N/R	N			N
103 W WASHINGTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
106 W WASHINGTON ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
120 S ALTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
110 S ALTON ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
106 S ALTON ST	N/A	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C	NL		N/R	N			N
104 S ALTON ST	N/A	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C	NL		N/R	N			N
102 S ALTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
105 W HIGH ST	N/A	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C	NL		N/R	N			N
10 S ALTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
10 S ALTON SUITE 1	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
10 S ALTON SUITE 2	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
102 W HIGH ST APT A	N/A	N	N	U	U	Visual Inspection	P	P	P	NL		N/R	N			N
102 W HIGH ST APT B	N/A	N	N	U	U	Visual Inspection	P	P	P	NL		N/R	N			N
102 W HIGH ST APT C	N/A	N	N	U	U	Visual Inspection	P	P	P	NL		N/R	N			N
102 W HIGH ST APT D	N/A	N	N	U	U	Visual Inspection	P	P	P	NL		N/R	N			N
8 S ALTON ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
6 S ALTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
5 S ALTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
4 S ALTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
2 S ALTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
101 N ALTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
105 N ALTON ST	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N
109 N ALTON ST	LC3T007	N	N	U	U	Survey Response	C	C	GRR	GRR	Y	N/R	N			N
203 N ALTON ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
207 N ALTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
209 N ALTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
301 N ALTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
305 N ALTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
307 N ALTON ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
309 N ALTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
311 N ALTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
405 N ALTON ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
411 N ALTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
501 N STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
9 W KOESTERER ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
408 N ALTON ST APT D	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
408 N ALTON ST APT C	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
408 N ALTON ST APT B	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
408 N ALTON ST APT A	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
402 N ALTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
312 N ALTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
308 N ALTON ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
302 N ALTON ST	LC3T025	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
212 N ALTON ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
208 N ALTON ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
206 N ALTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
202 N ALTON ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
104 N ALTON ST	N/A	N	N	U	U	Survey Response/Material Invoice	C	C	P	NL		N/R	N			N
106 N ALTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
108 N ALTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
110 N ALTON ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
10 N ALTON	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
11 S ALTON ST	LC5T038	Y	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N
7 W HIGH ST	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N
103 S ALTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
105 S ALTON ST	LC4T032	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
107 S ALTON ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
10 W WASHINGTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
12 W WASHINGTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
5 W WASHINGTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
201 S ALTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N

12 W APPLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
411 N STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
405 N STATE ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
401 N STATE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
311 N STATE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
307 N STATE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
301 N STATE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
211 N STATE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
203 N STATE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
201 N STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
105 N STATE	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
105 N STATE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
103 N STATE ST	N/A	N	N	U	U	Survey Response	P	P	P	NL		N/R	N			N
103 N STATE	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
2 S STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
4 S STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
8 S STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
2 W HIGH ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
1 W HIGH ST	N/A	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C	NL		N/R	N			N
302 S STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
306 S STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
310 S STATE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
312 S STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
406 S STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
410 S STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
502 S STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
506 S STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
508 S STATE ST	N/A	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C	NL		N/R	N			N
1 LINCOLN COURT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
600 S STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
830 S STATE ST	N/A	Y	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
840 S STATE	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
850 S STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
4 HILL MINE RD	N/A	Y	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N
351 HILL MINE RD	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
1032 S STATE ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
1109 S STATE ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
1215 S STATE ST	N/A	N	N	2/18/2022	2022	Survey Response/Logbook/Visual Inspection	C	C	P	NL		N/R	N			N
1230 S STATE ST	N/A	N	N	U	U	Construction Records	C	C	P	NL		N/R	N			N
1248 S STATE ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
7576 PRESS ROAD	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
1 COMMERCE DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
18 COMMERCE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
17 COMMERCE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
10 SOUTHGATE DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
20 SOUTHGATE DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
30 SOUTHGATE DR	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
32 SOUTHGATE DR	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
100 SOUTHGATE DR	N/A	N	N	U	U	Construction Records	C	C	P	NL		N/R	N			N
102 SOUTHGATE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
110 SOUTHGATE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
112 SOUTHGATE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
120 SOUTHGATE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
122 SOUTHGATE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
200 SOUTHGATE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
202 SOUTHGATE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
210 SOUTHGATE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
212 SOUTHGATE DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
220 SOUTHGATE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
223 SOUTHGATE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
221 SOUTHGATE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
300 SOUTHGATE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
302 SOUTHGATE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
304 SOUTHGATE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
306 SOUTHGATE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
308 SOUTHGATE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
310 SOUTHGATE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
332 SOUTHGATE APT 1	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
332 SOUTHGATE APT 2	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
332 SOUTHGATE APT 3	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
332 SOUTHGATE APT 4	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N

4 E WHITE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
2 N STATE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
4 N STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
6 N STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
12 N STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
102 N STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
106 N STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
108 N STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
110 N STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
112 N STATE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
202 N STATE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
206 N STATE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
208 N STATE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
212 N STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
302 N STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
304 N STATE ST	N/A	N	N	U	U	Visual Inspection	P	P	P	NL		N/R	N			N	
308 N STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
312 N STATE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
402 N STATE ST	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
409 N EDISON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
405 N EDISON ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
401 N EDISON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
311 N EDISON ST	LC3T009	N	N	U	U	Visual Inspection	C	C	GRR	GRR	Y	N/R	N			N	
307 N EDISON ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
301 N EDISON ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
211 N EDISON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
207 N EDISON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
203 N EDISON ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
201 N EDISON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
111 N EDISON ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
107 N EDISON ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
105 N EDISON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
11 E ST CLAIR ST	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
9 N EDISON ST	LC5T040	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
5 N EDISON ST	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
3 N EDISON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
11 E WHITE ST	LC3T010	N	N	U	U	Survey Response	C	C	GRR	GRR	Y	N/R	N			N	
12 E WHITE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
6 S EDISON ST	N/A	N	N	U	U	Visual Inspection/Visual Inspection	C	C	P	NL		N/R	N			N	
10 S EDISON ST	LC3T011	N	N	U	U	Visual Inspection/Visual Inspection	C	C	GRR	GRR	Y	N/R	N			N	
11 E HIGH ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
102 S EDISON ST	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
106 S EDISON ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
11 E WASHINGTON ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
8 E WASHINGTON ST	LC3T021	N	N	U	U	Visual Inspection/Visual Inspection	C	C	GRR	GRR		N/R	N			N	
10 E WASHINGTON ST	N/A	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C	NL		N/R	N			N	
113 E APPLE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
113 E APPLE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
112 E APPLE ST	LC3T001	N	N	U	U	Survey Response	C	C	C	NL		N/R	N	Y	3/19/2026	C	N
114 E APPLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
308 S CHERRY ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
310 S CHERRY ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
109 E EMILY ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
114 E EMILY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
116 E EMILY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
406 S CHERRY ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
117 E HILL ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
113 E HILL ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
109 E HILL ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
112 E HILL ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
114 E HILL ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
116 E HILL ST	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
201 E HILL ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
202 E HILL ST	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
205 E HILL ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
206 E HILL ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
209 E HILL ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
410 S VINE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
303 E HILL ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
401 S VINE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
210 E EMILY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	

118 E EMILY	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
304 S VINE ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
205 E EMILY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
206 E EMILY ST	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N
202 E EMILY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
311 S CHERRY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
202 E APPLE ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
204 E APPLE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
206 E APPLE ST	N/A	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C	NL		N/R	N			N
100 E WASHINGTON ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
109 S EDISON ST	LC3T020	N	N	U	U	Visual Inspection/Visual Inspection	C	C	GRR	GRR		N/R	N			N
107 S EDISON ST	N/A	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C	NL		N/R	N			N
105 S EDISON ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
101 S EDISON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
101 E HIGH ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
7 S EDISON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
5 S EDISON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
101 E WHITE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
6 N EDISON	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
8 N EDISON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
10 N EDISON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
101 E ST CLAIR ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
104 N EDISON ST	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N
108 N EDISON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
110 N EDISON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
112 N EDISON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
202 N EDISON ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
208 N EDISON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
212 N EDISON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
302 N EDISON ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
306 N EDISON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
310 N EDISON ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
101 E TEMPLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
410 N EDISON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
502 N EDISON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
409 N CHERRY ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
407 N CHERRY ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
405 N CHERRY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
109 E TEMPLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
110 E TEMPLE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
305 N CHERRY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
301R N CHERRY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
301 N CHERRY ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
211 N CHERRY ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
207 N CHERRY ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
203 N CHERRY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
201 N CHERRY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
111 N CHERRY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
111 E ST CLAIR ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
7 N CHERRY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
111 E WHITE ST	LC3T012	N	N	U	U	Visual Inspection	C	C	GRR	GRR	Y	N/R	N			N
2 S CHERRY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
8 S CHERRY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
12 S CHERRY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
112 E HIGH ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
106 S CHERRY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
108 S CHERRY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
111 E WASHINGTON ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
202 S CHERRY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
204 S CHERRY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
208 S CHERRY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
211 S CHERRY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
201 S CHERRY ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
107 S CHERRY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
105 S CHERRY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
201 E HIGH ST	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N
7 S CHERRY ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
201 E WHITE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
200 E WHITE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
4 N CHERRY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
8 N CHERRY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N

12 N CHERRY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
102 N CHERRY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
106 N CHERRY ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
112 N CHERRY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
202 N CHERRY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
204 N CHERRY ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
206 N CHERRY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
210 N CHERRY ST	LC3TD13	N	N	U	U	Survey Response	C	C	GRR	GRR	Y	N/R	N			N
200 E MILL ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
201 E MILL ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
202 E TEMPLE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
201 E TEMPLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
412 N CHERRY ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
411 N VINE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
410 N VINE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
411 N PITTS ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
414 N PITTS ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
412 N PITTS ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
401 E TEMPLE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
504 N PITTS ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
403 E TEMPLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
407 E TEMPLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
406 E TEMPLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
402 E TEMPLE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
400 E TEMPLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
307 E TEMPLE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
305 E TEMPLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
303 E TEMPLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
408 N VINE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
211 E TEMPLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
209 E TEMPLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
203 E TEMPLE ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
206 E TEMPLE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
208 E TEMPLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
300 E TEMPLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
306 E TEMPLE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
308 E TEMPLE ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
307 E MILL ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
305 E MILL ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
303 E MILL ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
301 E MILL ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
211 E MILL ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
209 E MILL ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
207 E MILL ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
205 E MILL ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
401 E MILL ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
405 E MILL ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
407 E MILL ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
409 E MILL ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
411 E MILL ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
7619 JACKS RUN RD	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
7606 JACKS RUN RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
422 E MILL ST	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N
501 E MILL ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
412 E MILL ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
414 E MILL ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
400 E MILL ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
318 A E MILL ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
318 B E MILL ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
306 E MILL ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
212 N VINE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
211 N VINE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
201 N VINE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
111 N VINE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
105 N VINE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
101 N VINE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
202 E ST CLAIR ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
7 N VINE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
5 N VINE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
3 N VINE ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
6 S VINE ST	N/A	N	N	2021	U	Logbook/Survey Response	P	P	P	NL		N/R	N			N
8 S VINE ST	LC3TD14	N	N	U	U	Survey Response	C	C	GRR	GRR	Y	N/R	N			N
10 S VINE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N

205 E HIGH ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
102 S VINE ST	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
104 S VINE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
106 S VINE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
108 S VINE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
112 S VINE ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
202 S VINE ST	LCAT045	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
206 S VINE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
210 S VINE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
207 E APPLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
300 S VINE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
301 S VINE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
302 S VINE ST	LC3T015	N	N	U	U	Visual Inspection	C	C	GRR	GRR	Y	N/R	N			N	
211 S VINE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
205 S VINE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
302 E WASHINGTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
111 S VINE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
105 S VINE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
101 S VINE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	Y	6/5/2023	Y	6/5/2023	C	N	
301 E HIGH ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
5 S VINE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
1 S VINE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
6 N VINE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
102 N VINE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
108 N VINE ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
110 N VINE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
112 N VINE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
302 ST CLAIR CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
304 ST CLAIR CT	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
306 ST CLAIR CT	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
308 E ST CLAIR CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
313 ST CLAIR CT	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
311 ST CLAIR CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
309 ST CLAIR CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
307 ST CLAIR CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
314 ST CLAIR CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
312 ST CLAIR CT	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
305 E HIGH ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
307 E HIGH ST	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
313 E HIGH ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
415 E HIGH ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
405 E HIGH ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
401 E HIGH ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
101 S PITTS ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
312 E HIGH ST	LC5T033	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	Y	2/22/2021	C	N	
106 S PITTS ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
112 S PITTS ST	LC3T017	N	N	U	U	Survey Response	C	C	GRR	GRR	Y	N/R	N			N	
105 S PITTS ST	N/A	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C	NL		N/R	N			N	
111 S PITTS ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
312 E WASHINGTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
206 S PITTS ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
212 S PITTS ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
301 S PITTS ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
303 S PITTS ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
407 CEMETERY ROAD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
417 CEMETERY ROAD	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
455 CEMETERY ROAD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
2 PALOMAR LAKE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
5 PALOMAR LAKE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
7 PALOMAR LAKE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
13 PALOMAR LAKE DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
519 CEMETERY RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
537 CEMETERY RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
601 HENDERSON POINTE TR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
541 CEMETERY RD	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
545 CEMETERY RD	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
549 CEMETERY RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
605 HENDERSON POINTE TR	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
609 HENDERSON POINTE TR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
755 CEMETERY ROAD	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
613 HENDERSON POINTE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
548 CEMETERY RD	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	

PARK METER	N/A	Y	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
310 E HILL - SWIM POOL	N/A	Y	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
311 OLD FAYETTEVILLE	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
601 ADELE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
609 ADELE ST	N/A	N	N	U	U	Survey Response	C	C	O	NL		N/R	N			N
410 SILVER ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
611 ADELE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
405 FIRST ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
1 MILFORD APT A	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
1 MILFORD APT B	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
1 MILFORD APT C	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
1 MILFORD APT D	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
2 MILFORD DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
3 MILFORD DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
4 MILFORD DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
5 A MILFORD DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
5 B MILFORD DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
6 MILFORD DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
7 MILFORD DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
8 MILFORD DR	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
9 MILFORD DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
10 B MILFORD DR	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
10A MILFORD DR	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
11 MILFORD DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
351 URBANNA DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
331 URBANNA DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
301 URBANNA DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
271 URBANNA DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
251 URBANNA DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
201 URBANNA DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
171 URBANNA DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
151 URBANNA DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
611 ELIZABETH DR	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
100 ELIZABETH DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
101 ELIZABETH DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
103 ELIZABETH DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
105 ELIZABETH DR	LC3T016	N	N	U	U	Construction Records	C	C	GRR	GRR	Y	N/R	N			N
107 ELIZABETH DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
203 ELIZABETH DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
605 CATHERINE CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
607 CATHERINE CT	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
608 CATHERINE CT	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
205 ELIZABETH DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
606 CATHERINE CT	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
607 PHIL-KATE CIRCLE	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
207 ELIZABETH DR	N/A	N	N	U	U	Construction Records	C	C	P	NL		N/R	N			N
605 PHIL-KATE CIRCLE	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
606 PHIL-KATE CIRCLE	N/A	N	N	U	U	Construction Records	C	C	P	NL		N/R	N			N
608 PHIL-KATE CIRCLE	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
610 PHIL-KATE CIRCLE	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
202 ELIZABETH DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
204 ELIZABETH DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
206 ELIZABETH DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
208 ELIZABETH DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
300 ELIZABETH DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
302 ELIZABETH DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
304 ELIZABETH DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
306 ELIZABETH DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
303 ELIZABETH DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
305 ELIZABETH DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
610 ADELE ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
608 ADELE ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
600 ADELE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
316 OLD FAYETTEVILLE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
312 OLD FAYETTEVILLE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
310 OLD FAYETTEVILLE	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
12 MEYER DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
13 MEYER DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
14 MEYER DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
15 MEYER DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
16 MEYER DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
17 MEYER DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
18 MEYER DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N

19 MEYER DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
20 MEYER DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
21 MEYER DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
22 MEYER DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
23 MEYER DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
24 MEYER DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
395 OLD FAYETTEVILLE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
2 PARK ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
4 PARK ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
6 PARK ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
8 PARK ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
10 PARK ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
12 PARK ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
14 PARK ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
13 PARK ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
11 PARK ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
9 PARK ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
7 PARK ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
5 PARK ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
3 PARK ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
1 PARK ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
415 OLD FAYETTEVILLE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
425 OLD FAYETTEVILLE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
630 DINTELMANN	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
600 DINTELMANN LN	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
700 KRISTIE LYNN ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
702 KRISTIE LYNN ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
11 WOODVIEW DR	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
710 KRISTIE LYNN ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
708 KRISTIE LYNN ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
704 KRISTIE LYNN ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
714 KRISTIE LYNN ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
715 KRISTIE LYNN ST	N/A	N	N	U	U	Construction Records/Survey Response	C	C	C	NL		N/R	N			N
713 KRISTIE LYNN ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
711 KRISTIE LYNN ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
709 KRISTIE LYNN ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
712 KRISTIE LYNN ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
10 WOODVIEW DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
703 KRISTIE LYNN ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
707 KRISTIE LYNN ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
706 KRISTIE LYNN ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
701 KRISTIE LYNN ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
705 KRISTIE LYNN ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
700 MARY ANN CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
702 MARY ANN CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
704 MARY ANN CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
706 MARY ANN CT	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
9 WOODVIEW DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
708 MARY ANN CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
710 MARY ANN CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
712 MARY ANN CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
714 MARY ANN CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
715 MARY ANN CT	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
713 MARY ANN CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
711 MARY ANN CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
709 MARY ANN CT	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
707 MARY ANN CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
7 WOODVIEW DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
705 MARY ANN CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
703 MARY ANN CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
701 MARY ANN CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
708 SAXONY LN	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
809 SAXONY LN	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
709 SAXONY LN	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
808 SAXONY LN	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N
8 WOODVIEW DR	N/A	N	N	11/16/2021	U	Survey Response/Logbook/Visual Inspection	C	C	C	NL		N/R	N			N
2 COUNTRY LANE	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
4 Country Lane	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
5 COUNTRY LANE	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
3 COUNTRY LANE	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
1 COUNTRY LANE	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
505 OLD FAYETTEVILLE	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N

1 EDGEWOOD CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
2 EDGEWOOD CT	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
3 EDGEWOOD CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
4 EDGEWOOD CT	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
5 EDGEWOOD CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
6 EDGEWOOD CT	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
7 EDGEWOOD CT	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
8 EDGEWOOD CT	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
9 EDGEWOOD CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
10 EDGEWOOD CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
400 BRICK LN	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
500 BRICK LN	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
11 EDGEWOOD CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
12 EDGEWOOD CT	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
13 EDGEWOOD CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
14 EDGEWOOD CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
15 EDGEWOOD CT	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
1 LAKEVIEW DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
3 LAKEVIEW DR	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
7 LAKEVIEW DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
9 LAKEVIEW DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
11 LAKEVIEW DR	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
13 LAKEVIEW DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
15 LAKEVIEW DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
17 LAKEVIEW DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
19 LAKEVIEW DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
21 LAKEVIEW DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
23 LAKEVIEW DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
25 LAKEVIEW DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
29 LAKEVIEW DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
27 LAKEVIEW DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
24 LAKEVIEW DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
28 LAKEVIEW DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
31 LAKEVIEW DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
33 LAKEVIEW DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
110 WILD CHERRY LN	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
568 CEMETERY ROAD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
35 LAKEVIEW DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
37 LAKEVIEW DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
32 LAKEVIEW DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
164 SUNRISE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
160 SUNRISE DR	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
150 SUNRISE DR	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
26 LAKEVIEW DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
22 LAKEVIEW DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
20 LAKEVIEW DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
18 LAKEVIEW DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
16 LAKEVIEW DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
14 LAKEVIEW DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
12 LAKEVIEW DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
10 LAKEVIEW DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
8 LAKEVIEW DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
6 LAKEVIEW DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
7 TRITT LANE	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
4 LAKEVIEW DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
2 LAKEVIEW DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
608 OLD FAYETTEVILLE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
603 OLD FAYETTEVILLE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
611 OLD FAYETTEVILLE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
615 OLD FAYETTEVILLE	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
602 OLD FAYETTEVILLE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
604 OLD FAYETTEVILLE	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
706 JACOBS LN	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
749 OLD FAYETTEVILLE RD	N/A	N	N	3/28/2022	U	Logbook/Visual Inspection/Survey Response	C	C	P	NL		N/R	N			N	
817 OLD FAYETTEVILLE	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
770 OLD FAYETTEVILLE RD	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
5108 WOUNDED KNEE TRAIL	N/A	N	N	U	U		C	C	P	NL		N/R	N			N	
5149 DOVETAIL	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
830 OLD FAYETTEVILLE RD	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
3708 STATE ROUTE 15	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
3702 STATE ROUTE 15	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
3658 STATE ROUTE 15	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	

755 URBANNA DR	N/A	N	N	2021	U	Survey Response/Logbook/Visual Inspection	C	C	C	NL	N/R	N	N
745 URBANNA DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
3 LAKE DR	N/A	N	N	U	U	Visual Inspection/Survey Response	C	C	C	NL	N/R	N	N
641 URBANNA DR	N/A	N	N	U	U	Survey Response	C	C	P	NL	N/R	N	N
635 URBANNA DR	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N
631 URBANNA DR	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N
7 DRACO DR	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N
5 DRACO DR	N/A	N	N	U	U	Survey Response	C	C	C	NL	N/R	N	N
102 WILLOW DR	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N
104 WILLOW DR	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N
106 WILLOW DR	N/A	N	N	U	U	Survey Response	C	C	C	NL	N/R	N	N
103 LAKE DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL	N/R	N	N
110 WILLOW DR	N/A	N	N	U	U	Construction Records	C	C	P	NL	N/R	N	N
107 WILLOW DR	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N
105 WILLOW DR	N/A	N	N	U	U	Survey Response	C	C	C	NL	N/R	N	N
103 WILLOW DR	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N
102 DRACO DR	N/A	N	N	U	U	Survey Response	C	C	C	NL	N/R	N	N
511 DRACO DR	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N
16 HICKORY DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
514 DRACO DR	N/A	N	N	U	U	Survey Response	C	C	P	NL	N/R	N	N
516 DRACO DR	N/A	N	N	U	U	Survey Response	C	C	P	NL	N/R	N	N
518 DRACO DR	N/A	N	N	U	U	Survey Response	C	C	P	NL	N/R	N	N
509 B DRACO DR	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N
509 A DRACO DR	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N
10 HICKORY DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
12 HICKORY DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
11 HICKORY DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
503 B DRACO DR	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N
503 A DRACO DR	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N
501 DRACO DR	N/A	N	N	U	U	Survey Response	C	C	C	NL	N/R	N	N
508 DRACO DR	N/A	N	N	U	U	Material Invoice	C	C	C	NL	N/R	N	N
510 DRACO DR	N/A	N	N	U	U	Material Invoice	C	C	P	NL	N/R	N	N
4 FRIEDA LANE	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N
5 FRIEDA LANE	N/A	N	N	U	U	Survey Response	C	C	P	NL	N/R	N	N
1 CYPRESS LANE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
315 LAKE DR	N/A	N	N	U	U	Visual Inspection	C	C	P	NL	N/R	N	N
314 LAKE DR	N/A	N	N	U	U	Visual Inspection	C	C	P	NL	N/R	N	N
308 LAKE DR	N/A	N	N	U	U	Visual Inspection	C	C	P	NL	N/R	N	N
746 URBANNA DR	N/A	Y	N	U	U	Survey Response/Visual Inspection	C	C	C	NL	N/R	N	N
746 URBANNA DR	N/A	Y	N	U	U	Survey Response/Visual Inspection	C	C	C	NL	N/R	N	N
655 URBANNA DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
654 SOLUTIONS DR	N/A	Y	N	U	U	Survey Response	C	C	C	NL	N/R	N	N
640 URBANNA DR	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N
630 URBANNA DR	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N
620 URBANNA DR	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N
610 URBANNA DR	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N
502 DRACO DR	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N
512 DRACO DR	N/A	N	N	U	U	Survey Response	C	C	P	NL	N/R	N	N
930 CEMETERY ROAD	N/A	N	N	U	U	Survey Response	C	C	C	NL	N/R	N	N
930 CEMETERY RD	N/A	N	N	U	U	Survey Response	C	C	P	NL	N/R	N	N
6467 WHITE OAKS CLUB RD	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL	N/R	N	N
83 BARBER LANE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
5501 BARBER LANE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
5505 BARBER LANE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
8457 RIVER KING RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N
100 WOODS MANOR DR	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N
102 WOODS MANOR DR	N/A	N	N	U	U	Survey Response	C	C	C	NL	N/R	N	N
200 WOODS MANOR DR	N/A	N	N	U	U	Construction Records	C	C	P	NL	N/R	N	N
202 WOODS MANOR DR	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N
204 WOODS MANOR DR	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N
300 WOODS MANOR DR	N/A	N	N	U	U	Survey Response	C	C	C	NL	N/R	N	N
302 WOODS MANOR DR	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N
304 WOODS MANOR DR	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N
500 WOODS MANOR DR	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N
502 WOODS MANOR DR	N/A	N	N	U	U	Survey Response	C	C	C	NL	N/R	N	N
504 WOODS MANOR DR	N/A	N	N	U	U	Survey Response	C	C	C	NL	N/R	N	N
507 WOODS MANOR DR	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N
505 WOODS MANOR DR	N/A	N	N	U	U	Survey Response	C	C	C	NL	N/R	N	N
503 WOODS MANOR DR	N/A	N	N	U	U	Survey Response	C	C	P	NL	N/R	N	N
203 WOODS MANOR DR	N/A	N	N	U	U	Survey Response	C	C	P	NL	N/R	N	N

500 SHADOW WOOD CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
502 SHADOW WOOD CT	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
504 SHADOW WOOD CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
506 SHADOW WOOD CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
507 SHADOW WOOD CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
505 SHADOW WOOD CT	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
503 SHADOW WOOD CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
501 SHADOW WOOD CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
101 WOODS MANOR DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
100 FOREST RIDGE CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
102 FOREST RIDGE CT	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
103 FOREST RIDGE CT	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
101 FOREST RIDGE CT	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
510 N EDISON	N/A	N	N	U	U	Material Invoice/Survey Response	C	C	C	NL		N/R	N			N
512 N EDISON	N/A	N	N	U	U	Survey Response/Material Invoice	C	C	C	NL		N/R	N			N
514 N EDISON	N/A	N	N	U	U	Material Invoice	C	C	C	NL		N/R	N			N
518 N EDISON	N/A	N	N	U	U	Material Invoice	C	C	C	NL		N/R	N			N
520 N EDISON	N/A	N	N	U	U	Material Invoice	C	C	P	NL		N/R	N			N
522 N EDISON	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
526 N EDISON	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
528 N EDISON	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
530 N EDISON ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
517 N EDISON	N/A	N	N	U	U	Material Invoice	C	C	C	NL		N/R	N			N
519 N EDISON	N/A	N	N	U	U	Survey Response/Material Invoice	C	C	P	NL		N/R	N			N
521 N EDISON	N/A	N	N	U	U	Material Invoice/Survey Response	C	C	C	NL		N/R	N			N
525 N EDISON	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
527 N EDISON	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
529 N EDISON	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
603 N EDISON ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
605 N EDISON ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
103 TALL MAPLE CT	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
109 TALL MAPLE CT	N/A	N	N	U	U	Material Invoice/Survey Response	C	C	P	NL		N/R	N			N
113 TALL MAPLE COURT	N/A	N	N	U	U	Material Invoice	C	C	C	NL		N/R	N			N
117 TALL MAPLE COURT	N/A	N	N	U	U	Material Invoice	C	C	C	NL		N/R	N			N
121 TALL MAPLE CT	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
125 TALL MAPLE CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
133 TALL MAPLE COURT	N/A	N	N	U	U	Material Invoice	C	C	C	NL		N/R	N			N
137 TALL MAPLE COURT	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
147 TALL MAPLE CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
148 TALL MAPLE CT	N/A	N	N	U	U	Survey Response/Material Invoice	C	C	C	NL		N/R	N			N
144 TALL MAPLE CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
120 TALL MAPLE COURT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
116 TALL MAPLE CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
512 CREEK RIDGE CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
508 CREEK RIDGE CT	N/A	N	N	U	U	Survey Response/Material Invoice	C	C	C	NL		N/R	N			N
504 CREEK RIDGE CT	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
500 CREEK RIDGE CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
501 CREEK RIDGE CT	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N
505 CREEK RIDGE CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
509 CREEK RIDGE CT	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
513 CREEK RIDGE CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
517 CREEK RIDGE CT	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
709 N EDISON ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
705 N EDISON ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
701 N EDISON ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
404 FIRESTONE	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
412 FIRESTONE	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
416 FIRESTONE ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
420 FIRESTONE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
429 FIRESTONE	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
405 FIRESTONE	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
612 FORD ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
621 FORD ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
2142 E ILLINOIS HWY 15	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
2134 E ILLINOIS HWY 15	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
2130 E ILLINOIS HWY 15	N/A	N	N	U	U	Visual Inspection/Survey Response	C	C	C	NL		N/R	N			N
3400 TWELVE OAKS LANE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N
1935 E ILLINOIS HWY 15	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
1885 E ILLINOIS HWY 15	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N
2219 E ILLINOIS HWY 15	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N

7723 JEFFERSON RD	N/A	N	N	U	U	Visual Inspection/Survey Response	C	C	C	NL	N/R	N	N				
7729 JEFFERSON RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N				
405 S STATE ST	N/A	Y	N	U	U	Survey Response	C	C	C	NL	N/R	N	N				
550 W PHILLIPS ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N				
801 N STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N				
2 COMMERCE DR	N/A	N	N	U	U	Survey Response	C	C	C	NL	N/R	N	N				
6 COMMERCE DR	N/A	N	N	U	U	Survey Response	C	C	C	NL	N/R	N	N				
1201 ANISE CT	N/A	N	N	U	U	Visual Inspection/Survey Response	C	C	C	NL	N/R	N	N				
901 WINGMEAD DR	N/A	N	N	U	U	Material Invoice/Visual Inspection	C	C	C	NL	N/R	N	N				
5490 BARBER LANE	N/A	N	N	U	U	Survey Response	C	C	C	NL	N/R	N	N				
5498 BARBER LANE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N				
5491 BARBER LANE	N/A	N	N	U	U	Material Invoice/Survey Response	C	C	P	NL	N/R	N	N				
5483 BARBER LANE	N/A	N	N	U	U	Survey Response	C	C	C	NL	N/R	N	N				
5469 BARBER LANE	N/A	N	N	U	U	Survey Response	C	C	C	NL	N/R	N	N				
5451 BARBER LANE	N/A	N	N	U	U	Survey Response	C	C	P	NL	N/R	N	N				
5440 BARBER LANE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N				
5512 BARBER LANE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N				
5456 BARBER LANE	N/A	N	N	U	U	Survey Response	C	C	P	NL	N/R	N	N				
5462 BARBER LANE	N/A	N	N	U	U	Material Invoice	C	C	C	NL	N/R	N	N				
900 WINGMEAD DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N				
5467 OAK THORN DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL	N/R	N	N				
5459 OAK THORN DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N				
5451 OAK THORN DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL	N/R	N	N				
5443 OAK THORN DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N				
5435 OAK THORN DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N				
5427 OAK THORN DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N				
5426 OAK THORN DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N				
5434 OAK THORN DR	N/A	N	N	U	U	Material Invoice/Survey Response/Visual Inspection	C	C	C	NL	N/R	N	N				
5444 OAK THORN DR	N/A	N	N	U	U	Material Invoice/Survey Response/Visual Inspection	C	C	C	NL	N/R	N	N				
918 BAY POINTE DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL	N/R	N	N				
926 BAY POINTE DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL	N/R	N	N				
934 BAY POINTE DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N				
942 BAY POINTE DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N				
950 BAY POINTE DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL	N/R	N	N				
957 BAY POINTE DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL	N/R	N	N				
941 BAY POINTE DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL	N/R	N	N				
933 BAY POINTE DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL	N/R	N	N				
925 BAY POINTE DR	N/A	N	N	U	U	Material Invoice/Survey Response/Visual Inspection	C	C	P	NL	N/R	N	N				
917 BAY POINTE DR	N/A	N	N	U	U	Visual Inspection	C	C	P	NL	N/R	N	N				
5460 OAK THORN DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL	N/R	N	N				
918 WINGMEAD DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL	N/R	N	N				
924 WINGMEAD DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL	N/R	N	N				
925 WINGMEAD DR	N/A	N	N	U	U	Material Invoice/Survey Response	C	C	P	NL	N/R	N	N				
917 WINGMEAD DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N				
924 PROMONTORY PINES	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL	N/R	N	N				
932 PROMONTORY PINES	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL	N/R	N	N				
964 PROMONTORY PINES	N/A	N	N	U	U	Material Invoice/Survey Response	C	C	C	NL	N/R	N	N				
972 PROMONTORY PINES	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N				
980 PROMONTORY PINES	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N				
955 PROMONTORY PINES	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL	N/R	N	N				
947 PROMONTORY PINES	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N				
931 PROMONTORY PINES	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N				
923 PROMONTORY PINES	LCAT044	N	N	U	U	Visual Inspection	C	C	P	NL	N/R	N	N				
903 PROMONTORY PINES	N/A	N	N	U	U	Visual Inspection	C	C	C	NL	N/R	N	N				
1017 TORRINGTON LN	N/A	N	N	U	U	Material Invoice/Survey Response	C	C	C	NL	N/R	N	N				
1013 TORRINGTON LN	N/A	N	N	U	U	Survey Response/Material Invoice	C	C	P	NL	N/R	N	N				
1009 TORRINGTON LN	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N				
1005 TORRINGTON LN	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N				
1001 TORRINGTON LN	N/A	N	N	U	U	Survey Response	C	C	C	NL	N/R	N	N				
300 CHIMNEY ROCK DR	N/A	N	N	U	U	Survey Response	C	C	C	NL	N/R	N	N				
308 CHIMNEY ROCK DR	N/A	N	N	U	U	Construction Records	C	C	C	NL	N/R	N	N				
312 CHIMNEY ROCK DR	N/A	N	N	U	U	Construction Records	C	C	P	NL	N/R	N	N				

316 CHIMNEY ROCK DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
320 CHIMNEY ROCK DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
324 CHIMNEY ROCK DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
404 CHIMNEY ROCK DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
408 CHIMNEY ROCK DR	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
328 CHIMNEY ROCK DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
332 CHIMNEY ROCK DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
315 CHIMNEY ROCK DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
409 CHIMNEY ROCK DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
401 CHIMNEY ROCK	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
335 CHIMNEY ROCK DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
331 CHIMNEY ROCK DR	N/A	N	N	U	U	Material Invoice	C	C	C	NL		N/R	N			N
327 CHIMNEY ROCK DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
321 CHIMNEY ROCK DR	N/A	N	N	U	U	Material Invoice/Survey Response	C	C	C	NL		N/R	N			N
1000 TORRINGTON LN	N/A	N	N	U	U	Construction Records/Survey Response	C	C	P	NL		N/R	N			N
309 CHIMNEY ROCK	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
1004 TORRINGTON LN	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
304 GLENROCK LN	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
308 GLENROCK LN	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
312 GLENROCK LN	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
316 GLENROCK LN	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
320 GLENROCK LN	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
324 GLENROCK LN	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
328 GLENROCK LN	N/A	N	N	U	U	Survey Response/Material Invoice	C	C	C	NL		N/R	N			N
333 GLENROCK LN	N/A	N	N	U	U	Construction Records	C	C	P	NL		N/R	N			N
329 GLENROCK LN	N/A	N	N	U	U	Material Invoice	C	C	C	NL		N/R	N			N
325 GLENROCK LN	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
321 GLENROCK LN	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
317 GLENROCK LN	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
313 GLENROCK LN	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
309 GLENROCK LN	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
305 GLENROCK LN	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
1012 TORRINGTON LN	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
304 SLEEPING INDIAN	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
308 SLEEPING INDIAN DR	N/A	N	N	U	U	Construction Records	C	C	P	NL		N/R	N			N
312 SLEEPING INDIAN DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
324 SLEEPING INDIAN DR	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
328 SLEEPING INDIAN DR	N/A	N	N	U	U	Material Invoice/Survey Response	C	C	C	NL		N/R	N			N
332 SLEEPING INDIAN DR	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
340 SLEEPING INDIAN DR	N/A	N	N	U	U	Material Invoice	C	C	C	NL		N/R	N			N
354 SLEEPING INDIAN DR	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
358 SLEEPING INDIAN DR	N/A	N	N	U	U	Material Invoice/Survey Response	C	C	C	NL		N/R	N			N
362 SLEEPING INDIAN DR	N/A	N	N	U	U	Material Invoice	C	C	C	NL		N/R	N			N
366 SLEEPING INDIAN DR	N/A	N	N	U	U	Material Invoice	C	C	C	NL		N/R	N			N
371 SLEEPING INDIAN DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
343 SLEEPING INDIAN DR	N/A	N	N	U	U	Survey Response/Material Invoice	C	C	C	NL		N/R	N			N
325 SLEEPING INDIAN DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
321 SLEEPING INDIAN DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
309 SLEEPING INDIAN DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
313 TORRINGTON LN	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
304 TORRINGTON LN	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
308 TORRINGTON LN	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
312 TORRINGTON LN	N/A	N	N	U	U	Material Invoice	C	C	C	NL		N/R	N			N
316 TORRINGTON LN	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
320 TORRINGTON LN	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
317 TORRINGTON LN	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
309 TORRINGTON LN	N/A	N	N	U	U	Survey Response/Material Invoice	C	C	C	NL		N/R	N			N
201 SLEEPING INDIAN DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
300 SILVERTHORNE DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
304 SILVERTHORNE DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
308 SILVERTHORNE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
312 SILVERTHORNE DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
316 SILVERTHORNE DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
320 SILVERTHORNE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
324 SILVERTHORNE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
336 SILVERTHORNE DR	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
400 SILVERTHORNE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
408 SILVERTHORNE	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
412 SILVERTHORNE DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
416 SILVERTHORNE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
420 SILVERTHORNE DR	N/A	N	N	U	U	Construction Records	C	C	P	NL		N/R	N			N

419 SILVERTHORNE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
403 SILVERTHORNE DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
400 TELLURIDE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
404 SILVERTHORNE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
407 SILVERTHORNE DR	N/A	N	N	U	U	Material Invoice	C	C	C	NL		N/R	N			N	
415 SILVERTHORNE DR	N/A	N	N	U	U	Material Invoice/Survey Response	C	C	P	NL		N/R	N			N	
409 TELLURIDE DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
405 TELLURIDE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
413 TELLURIDE DR	N/A	N	N	U	U	Construction Records	C	C	P	NL		N/R	N			N	
417 TELLURIDE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
412 TELLURIDE DR	N/A	N	N	U	U	Survey Response/Material Invoice	C	C	C	NL		N/R	N			N	
401 TELLURIDE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
408 TELLURIDE DR	N/A	N	N	U	U	Construction Records	C	C	P	NL		N/R	N			N	
404 TELLURIDE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
313 TELLURIDE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
309 TELLURIDE DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
301 TELLURIDE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
300 TELLURIDE DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
304 TELLURIDE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
308 TELLURIDE DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
312 TELLURIDE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
337 SILVERTHORNE DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
333 SILVERTHORNE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
325 SILVERTHORNE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
321 SILVERTHORNE DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
317 SILVERTHORNE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
313 SILVERTHORNE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
309 SILVERTHORNE DR	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
305 SILVERTHORNE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
301 SILVERTHORNE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
224 ALAMOSA DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
222 ALAMOSA DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
228 ALAMOSA DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
226 ALAMOSA DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
209 ALAMOSA DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
225 ALAMOSA DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
211 ALAMOSA DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
213 ALAMOSA DR	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
215 ALAMOSA DR	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
217 ALAMOSA DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
219 ALAMOSA DR	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
221 ALAMOSA DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
223 ALAMOSA DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
227 ALAMOSA DR	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
229 ALAMOSA DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
231 ALAMOSA DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
233 ALAMOSA DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
235 ALAMOSA DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
205 ALAMOSA DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
207 ALAMOSA DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
201 ALAMOSA DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
203 ALAMOSA DR	N/A	N	N	U	U	Construction Records	C	C	P	NL		N/R	N			N	
200 ALAMOSA DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
202 ALAMOSA DR	N/A	N	N	U	U	Construction Records/Survey Response	C	C	C	NL		N/R	N			N	
204 ALAMOSA DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
206 ALAMOSA DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
205 SILVERTHORNE DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
207 SILVERTHORNE DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
201 SILVERTHORNE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N	
203 SILVERTHORNE DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
218 ALAMOSA DR	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
220 ALAMOSA DR	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
328 SILVERTHORNE DR	N/A	N	N	U	U	Material Invoice	C	C	C	NL		N/R	N			N	
329 SILVERTHORNE DR	N/A	N	N	U	U	Material Invoice	C	C	C	NL		N/R	N			N	
553 CEMETERY ROAD	N/A	N	N	U	U	Material Invoice/Survey Response	C	C	C	NL		N/R	N			N	
305 TORRINGTON LN	N/A	N	N	U	U	Material Invoice	C	C	C	NL		N/R	N			N	
316 SLEEPING INDIAN DR	N/A	N	N	U	U	Material Invoice	C	C	C	NL		N/R	N			N	
3709 STATE ROUTE 15	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
3713 STATE ROUTE 15	N/A	N	N	U	U	Material Invoice	C	C	C	NL		N/R	N			N	
416 TELLURIDE DR	N/A	N	N	U	U	Material Invoice	C	C	P	NL		N/R	N			N	
506 DRACO DR	N/A	N	N	U	U	Material Invoice	C	C	C	NL		N/R	N			N	
504 DRACO DR	N/A	N	N	U	U	Material Invoice	C	C	C	NL		N/R	N			N	

305 SLEEPING INDIAN DR	N/A	N	N	U	U	Material Invoice	C	C	C	NL		N/R	N			N
332 SILVERTHORNE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
301 TORRINGTON	N/A	N	N	U	U	Material Invoice	C	C	C	NL		N/R	N			N
1 CHERRY TREE LN	N/A	N	N	U	U	Material Invoice	C	C	C	NL		N/R	N			N
313 SLEEPING INDIAN DR	N/A	N	N	U	U	Material Invoice	C	C	C	NL		N/R	N			N
3719 STATE ROUTE 15	N/A	N	N	U	U	Survey Response/Material Invoice	C	C	C	NL		N/R	N			N
210 ALAMOSA DR	N/A	N	N	U	U	Material Invoice/Survey Response	C	C	C	NL		N/R	N			N
212 ALAMOSA DR	N/A	N	N	U	U	Material Invoice/Survey Response	C	C	C	NL		N/R	N			N
7632 JEFFERSON RD	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
7716 JEFFERSON RD	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
7730 JEFFERSON RD	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
7736 JEFFERSON RD	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
7718 JEFFERSON RD	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
7708 KAMPER COTTAGE LANE	N/A	N	N	U	U	Material Invoice	C	C	C	NL		N/R	N			N
7709 KAMPER COTTAGE LANE	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
3042 SAVE RD	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
3122 SAVE ROAD	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
3001 SAVE RD	N/A	N	N	U	U	Construction Records	C	C	P	NL		N/R	N			N
3121 SAVE ROAD	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N
320 SLEEPING INDIAN DR	N/A	N	N	U	U	Material Invoice	C	C	C	NL		N/R	N			N
3731 STATE ROUTE 15	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
3831 STATE ROUTE 15	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
3837 STATE ROUTE 15	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
400 CHIMNEY ROCK DR	N/A	N	N	U	U	Material Invoice	C	C	P	NL		N/R	N			N
3901 STATE ROUTE 15	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
3921 STATE ROUTE 15	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
214 ALAMOSA DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
216 ALAMOSA DR	N/A	N	N	U	U	Material Invoice/Survey Response	C	C	C	NL		N/R	N			N
3714 STATE ROUTE 15	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
520 URBANNA DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
3646 STATE ROUTE 15	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
3726 STATE ROUTE 15	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
3725 STATE ROUTE 15	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
3735 STATE ROUTE 15	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
7831 JEFFERSON RD	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
3746 STATE ROUTE 15	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
3750 STATE ROUTE 15	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
3756 STATE ROUTE 15	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N
3806 STATE ROUTE 15	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
3812 STATE ROUTE 15	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
7843 JEFFERSON RD	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
367 SLEEPING INDIAN DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
3824 STATE ROUTE 15	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
300 SLEEPING INDIAN DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
3818 STATE ROUTE 15	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N
401 FOXTAIL DR	N/A	N	N	U	U	Visual Inspection	P	P	P	NL		N/R	N			N
405 FOXTAIL DR	N/A	N	N	U	U	Visual Inspection	P	P	P	NL		N/R	N			N
409 FOXTAIL DR	N/A	N	N	U	U	Visual Inspection	P	P	P	NL		N/R	N			N
417 FOXTAIL DR	N/A	N	N	U	U	Visual Inspection	P	P	P	NL		N/R	N			N
421 FOXTAIL DR	N/A	N	N	U	U	Visual Inspection	P	P	P	NL		N/R	N			N
429 FOXTAIL DRIVE	N/A	N	N	U	U	Logbook/Visual Inspection/Survey Response	P	P	P	NL		N/R	N			N
437 FOXTAIL DR	N/A	N	N	U	U	Visual Inspection	P	P	P	NL		N/R	N			N
441 FOXTAIL DR	N/A	N	N	2021	2021	Visual Inspection	P	P	P	NL		N/R	N			N
445 FOXTAIL DR	N/A	N	N	U	U	Visual Inspection	P	P	P	NL		N/R	N			N
444 FOXTAIL DR	N/A	N	N	4/8/2021	2021	Logbook/Visual Inspection	C	C	P	NL		N/R	N			N
436 FOXTAIL DR	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N
424 FOXTAIL DR	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N
420 FOXTAIL DR	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N
416 FOXTAIL DR	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N
408 FOXTAIL DR	N/A	N	N	U	U	Visual Inspection	P	P	P	NL		N/R	N			N
400 FOXTAIL DR	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N
1013 Torrey Lane	N/A	N	N	2021	2021	Logbook/Visual Inspection	P	P	P	NL		N/R	N			N
1009 TORREY LANE	N/A	N	N	2021	2021	Logbook/Visual Inspection	P	P	P	NL		N/R	N			N
1005 TORREY LANE	N/A	N	N	4/9/2021	2021	Survey Response/Logbook/Visual Inspection	P	P	P	NL		N/R	N			N
1004 TORREY LANE	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N
711 W APPLE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N
727 W APPLE ST	LC3TD18	N	N	U	U	Visual Inspection	C	C	GRR	GRR	Y	N/R	N			N
906 W APPLE ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N			N

810 W APPLE ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N				N
806 W APPLE ST	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N				N
7 CHERRY TREE LN	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N				N
712 W APPLE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N				N
10 CHERRY TREE LN	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N				N
709 KESSLER RD	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N				N
705 KESSLER RD	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N				N
815 KESSLER RD	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N				N
903 WOLF RD	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N				N
501 N MAIN ST	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N				N
406 FIRST ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N
371 URBANNA DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N
150 WILD CHERRY LANE	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N				N
125 SUNRISE DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N
170 SUNRISE DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N
113 SUNRISE DR	N/A	N	N	U	U	Visual Inspection/Survey Response	C	C	C	NL		N/R	N				N
616 OLD FAYETTEVILLE	N/A	N	N	U	U		C	C	C	NL		N/R	N				N
621 OLD FAYETTEVILLE RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N
629 OLD FAYETTEVILLE RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N
701 JACOBS LANE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N
641 OLD FAYETTEVILLE RD	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N				N
624 OLD FAYETTEVILLE	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N				N
632 OLD FAYETTEVILLE RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N
731 SHADY LANE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N
732 SHADY LANE	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N				N
744 SHADY LANE	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N				N
712 SHADY LANE	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N				N
801 OLD FAYETTEVILLE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N
809 OLD FAYETTEVILLE	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N				N
821 OLD FAYETTEVILLE	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N				N
829 OLD FAYETTEVILLE	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N				N
900 OLD FAYETTEVILLE RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N
912 OLD FAYETTEVILLE RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N
914 OLD FAYETTEVILLE RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N
916 OLD FAYETTEVILLE RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N
915 OLD FAYETTEVILLE RD	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N				N
926 OLD FAYETTEVILLE RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N
927 OLD FAYETTEVILLE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N
945 OLD FAYETTEVILLE RD	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N				N
3904 STATE ROUTE 15	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N				N
3922 STATE ROUTE 15	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N				N
3910 STATE ROUTE 15	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N				N
3926 STATE ROUTE 15	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N				N
3858 STATE ROUTE 15	N/A	N	N	U	U	Construction Records	C	C	P	NL		N/R	N				N
3834 STATE ROUTE 15	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N				N
3830 STATE ROUTE 15	N/A	N	N	U	U	Construction Records	C	C	P	NL		N/R	N				N
3815 STATE ROUTE 15	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N				N
3761 STATE ROUTE 15	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N				N
3857 STATE ROUTE 15	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N				N
3745 STATE ROUTE 15	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N				N
3744 STATE ROUTE 15	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N				N
3738 STATE ROUTE 15	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N				N
3732 STATE ROUTE 15	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N				N
3720 STATE ROUTE 15	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N				N
3703 STATE ROUTE 15	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N				N
3640 STATE ROUTE 15	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N				N
3641 STATE ROUTE 15	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N				N
3619 STATE ROUTE 15	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N				N
3623 STATE ROUTE 15	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N				N
733 URBANNA DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N
599 URBANNA DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N
550 URBANNA DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N
767 CEMETERY ROAD	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N				N
769 CEMETERY ROAD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N
710 CEMETERY ROAD	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N				N
716 CEMETERY ROAD	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N				N
740 CEMETERY ROAD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N
750 CEMETERY ROAD	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N				N
771 CEMETERY ROAD	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N				N
811 CEMETERY ROAD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N
815 CEMETERY ROAD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N
819 CEMETERY ROAD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N
820 CEMETERY ROAD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N

821 CEMETERY ROAD	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
833 CEMETERY ROAD	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N			N	
90 PRESTON DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
30 PRESTON DR	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
873 CEMETERY ROAD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
889 CEMETERY RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
901 CEMETERY RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
97 BARBER LANE	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
5520 BARBER LANE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
120 BARBER LANE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
5733 BARBER LANE	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
155 BARBER LANE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
970 CEMETERY ROAD	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
967 CEMETERY ROAD	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
5765 BARBER LANE	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N			N	
5913 BARBER LANE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
5807 BARBER LANE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
8330 JACKS RUN RD	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
5855 BARBER LANE	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
8362 WOODLAND PATH	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
8367 WOODLAND PATH	N/A	N	N	U	U	Visual Inspection/Survey Response	C	C	P	NL		N/R	N			N	
8343 WOODLAND PATH	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
8300 WOODLAND PATH	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
8338 WOODLAND PATH	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
8331 WOODLAND PATH	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
8315 WOODLAND PATH	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
5909 BARBER LANE	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N			N	
8342 JACKS RUN RD	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
5930 MOON LANE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
5901 MOON LANE	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
BARBER LANE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
8262 JACKS RUN RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
8312 JACKS RUN RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
8324 JACKS RUN RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
8443 RIVER KING DR TRAILR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
8380 PEABODY RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
8451 RIVER KING DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
8114 PEABODY RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
8115 PEABODY RD	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
8123 PEABODY RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
8131 PEABODY RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
8139 PEABODY RD	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
8201 PEABODY RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
8209 PEABODY RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
8217 PEABODY RD	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
8225 PEABODY RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
8233 PEABODY RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
8241 PEABODY RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
8301 PEABODY RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
8309 PEABODY RD	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
8317 PEABODY RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
8325 PEABODY RD	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
8326 HERON COVE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
8318 HERON COVE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
8310 HERON COVE	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
8302 HERON COVE	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
8311 HERON COVE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
8323 HERON COVE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
8403 HERON COVE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
8410 HERON COVE	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
8402 HERON COVE	N/A	N	N	U	U	Visual Inspection/Survey Response	C	C	C	NL		N/R	N			N	
8403 RIVER KING DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
8411 RIVER KING DR	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	
8419 RIVER KING DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N			N	
8427 RIVER KING DR	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N			N	
8435 River King Drive	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N			N	

8324 PEABODY RD	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N				N	
8316 PEABODY RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
8306 PEABODY RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
8238 PEABODY RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
8230 PEABODY RD	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N				N	
8216 PEABODY RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
8204 PEABODY RD	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
8122 PEABODY RD	N/A	N	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N				N	
8435 RIVER KING DR	N/A	N	N	U	U	Material Invoice/Survey Response	C	C	C	NL		N/R	N				N	
8105 PEABODY RD	N/A	N	N	U	U	Material Invoice/Visual Inspection	C	C	C	NL		N/R	N				N	
361 TOWN & COUNTRY	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
500 N STATE ST	N/A	Y	N	U	U	Survey Response/Visual Inspection	C	C	P	NL		N/R	N				N	
701 S STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
800 S STATE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N				N	
820 S STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N				N	
409 W APPLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
408 S BELLEVILLE	N/A	Y	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N				N	
408 S BELLEVILLE	N/A	Y	N	U	U	Survey Response/Visual Inspection	O	O	O	NL		N/R	N				N	
408 S BELLEVILLE ST	N/A	Y	N	U	U	Survey Response/Visual Inspection	O	O	O	NL		N/R	N				N	
408 S BELLEVILLE	N/A	Y	N	U	U		C	C	C	NL		N/R	N				N	
401 S MONROE ST	N/A	Y	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
401 S MONROE ST	N/A	Y	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
SOFTBALL/BASEBALL DIAMOND	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
CONCESSION STAND	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
401 S MONROE	N/A	Y	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
804 N STATE ST	N/A	Y	N	U	U	Survey Response	C	C	C	NL		N/R	N				N	
804 N STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
21 SOUTHGATE DR	N/A	N	N	U	U	Survey Response	C	C	P	NL		N/R	N				N	
108 S STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
102 N ALTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
715 N STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N				N	
408 S BELLEVILLE ST	N/A	Y	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
202 S STATE	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N				N	
202 S STATE	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
210 W WHITE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N				N	
311 S STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
1799 N STATE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N				N	
707 N STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
7 N BELLEVILLE ST	N/A	Y	N	U	U	Survey Response	C	C	C	NL		N/R	N				N	
9 N ALTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
6 N ALTON ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
2 N ALTON ST	N/A	Y	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
410 W WASHINGTON ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N				N	
900 N STATE ST	N/A	Y	N	U	U	Survey Response	C	C	P	NL		N/R	N				N	
11 SOUTHGATE CENTER	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N				N	
14 SOUTHGATE CENTER	N/A	Y	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
750 S STATE	N/A	Y	N	U	U	Survey Response/Visual Inspection	O	O	O	NL		N/R	N				N	
416 S RICHLAND ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
502 S RICHLAND BLDG 1A	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
502 S RICHLAND BLDG 2	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
3 S BELLEVILLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
501 W APPLE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
5516 WILLOW SPRINGS LN	N/A	N	N	U	U	Visual Inspection	P	P	C	NL		N/R	N				N	
5 W APPLE ST	N/A	Y	N	U	U	Survey Response/Visual Inspection	C	C	C	NL		N/R	N				N	
751 S STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
708 N STATE ST	N/A	Y	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
708 N STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
800 N STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
407 S BELLEVILLE ST	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N				N	
301 S STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
860 S STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
1231 N STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	C	NL		N/R	N				N	
5 COMMERCE DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N				N	
10 COMMERCE DR	N/A	N	N	U	U	Survey Response	C	C	C	NL		N/R	N				N	
9 INDUSTRIAL DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N				N	
1210 N STATE	N/A	N	N	U	U	Visual Inspection	P	P	C	NL		N/R	N				N	
1414 SOUTH STATE ST	N/A	N	N	U	U	Visual Inspection	C	C	P	NL		N/R	N				N	
2 INDUSTRIAL DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N				N	
4 INDUSTRIAL DR	N/A	N	N	U	U	Construction Records	C	C	C	NL		N/R	N				N	

