



Lead Service Line Inventory 2024

Water System Name: Freeburg PWS

System ID Number: IL1630600

Current Inventory Date: 04/15/2025

Previous Inventory Date: 4/15/2024

Has Funding Assistance Been Requested?: NO

Service Address	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property
	Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line identified? <b>EXAMPLES:</b> Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	If any Galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the Galvanized service line material was never downstream of any Lead section, mark No (N).  If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead  If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line replaced.  Leave blank if previous column was (N).	C - No Lead Solder (C)	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver.  Leave blank if customer has not refused access.
	Yes (Y) or No (N)				Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)								
					Galvanized (G)	Galvanized (G)	Galvanized (G)								
					Lead (L)	Galvanized Requiring Replacement (GRR)	Galvanized Requiring Replacement (GRR)								
					Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)								
					Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)								
					Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)								
					Unknown Not Lead (UNL)	Unknown (U)	Unknown (U)								
						Unknown Not Lead (UNL)	Unknown Not Lead (UNL)								
601 W Apple Street	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
605 W Apple Street	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1 Briarwood Court	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
10 Briarwood Court	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
11 Briarwood Court	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
12 Briarwood Court	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
2 Briarwood Court	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
3 Briarwood Court	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
4 Briarwood Court	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
5 Briarwood Court	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
6 Briarwood Court	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
7 Briarwood Court	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8 Briarwood Court	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
9 Briarwood Court	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
606 W Apple Street	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
617 W Apple Street	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
619 W Apple Street	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1 Sunset Drive 5/6	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1 Sunset Drive Apt 10	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
1 Sunset Drive Apt 1	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1 Sunset Drive Apt 2	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1 Sunset Drive Apt 3	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1 Sunset Drive Apt 4	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	

1 Sunset Drive Apt 7	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1 Sunset Drive Apt 8	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1 Sunset Drive Apt 9	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
7 Sunset Drive Apt A	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
7 Sunset Drive Apt B	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
7 Sunset Drive Apt C	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8 Sunset Drive Apt C	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8 Sunset Drive Apt B	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8 Sunset Drive Apt A	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
6 SUNSET DR APT D	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
6 SUNSET DR APT C	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
6 SUNSET DR APT B	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
6 SUNSET DR APT A	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
4 SUNSET DR APT 4	N	N	U	U	Visual Inspection/Survey Response	C	C	C		N/R	N			N	
4 SUNSET DR APT 3	N	N	U	U	Visual Inspection/Survey Response	C	C	C		N/R	N			N	
4 SUNSET DR APT 2	N	N	U	U	Visual Inspection/Survey Response	C	C	C		N/R	N			N	
4 SUNSET DR APT 1	N	N	U	U	Visual Inspection/Survey Response	C	C	C		N/R	N			N	
2 SUNSET DR APT 1	N	N	U	U	Visual Inspection/Survey Response	C	C	C		N/R	N			N	
2 SUNSET DR APT 2	N	N	U	U	Visual Inspection/Survey Response	C	C	C		N/R	N			N	
2 SUNSET DR APT 3	N	N	U	U	Visual Inspection/Survey Response	C	C	C		N/R	N			N	
2 SUNSET DR APT 4	N	N	U	U	Visual Inspection/Survey Response	C	C	C		N/R	N			N	
5 SUNSET DR APT A	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
5 SUNSET DR APT B	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
5 SUNSET DR APT C	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
5 SUNSET DR APT D	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
5 SUNSET DR APT E	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
5 SUNSET DR APT F	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
5 SUNSET DR APT G	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
5 SUNSET DR APT H	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
1005 W APPLE ST	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
5420 WILLOW SPRINGS LN	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
5490 WILLOW SPRINGS LANE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
5535 WILLOW SPRINGS LN	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
1041 W APPLE ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
1057 W APPLE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
1208 W APPLE ST	N	N	U	U	Construction Records	P	P	P		N/R	N			N	
109 S WEST ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
107 S WEST ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
105 S WEST ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
101 S WEST ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
2 CHERRY TREE LN	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
3 CHERRY TREE LN	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
4 CHERRY TREE LN	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
6 CHERRY TREE LN	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
606 W HIGH ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
604 W HIGH ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
602 W HIGH ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	

8 S POTTER ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
6 S POTTER ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
2 S POTTER ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
1 N POTTER ST	N	N	U	U	Visual Inspection/Survey Response	C	C	C		N/R	N			N	
1 A N POTTER ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
3 N POTTER ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
5 N POTTER ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
6 N POTTER ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
4 N POTTER ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
2 N POTTER ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1 S POTTER ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
3 S POTTER ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
504 W HIGH ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
505 W HIGH ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
601 W HIGH ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
2 N WEST ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
9 N WEST ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
7 N WEST ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
3 N WEST ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
4 N WEST ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
1 N WEST ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
1 S WEST ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
701 KESSLER RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
102 WESTVIEW DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
104 WESTVIEW DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
108 WESTVIEW DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
110 WESTVIEW DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
112 WESTVIEW DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
114 WESTVIEW DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
118 WESTVIEW DR	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
120 WESTVIEW DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
906 WOLF RD	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
1244 WOLF RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1238 WOLF RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1230 WOLF ROAD	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
1220 WOLF RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1207 WOLF RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1201 WOLF RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1203 WOLF RD	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
601 NIEBRUEGGE LN	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1209 WOLF RD	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
600 NIEBRUEGGE LN	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
651 NIEBRUEGGE LN	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
650 NIEBRUEGGE LN	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
701 NIEBRUEGGE LN	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
700 NIEBRUEGGE LN	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
711 NIEBRUEGGE LN	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
750 NIEBRUEGGE LN	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
751 NIEBRUEGGE LN	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
801 NIEBRUEGGE LN	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
811 NIEBRUEGGE LN	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	

851 NIEBRUEGGE LN	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
901 NIEBRUEGGE LN	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
850 CABIN CREEK	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
860 CABIN CREEK	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
1001 NIEBRUEGGE LN	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1000 NIEBRUEGGE LN	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1140 NIEBRUEGGE LANE	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
1150 NIEBRUEGGE LN	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1248 WOLF RD	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
800 NIEBRUEGGE LN	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
1252 WOLF RD	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
1225 WOLF RD	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
1237 WOLF RD	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
1241 WOLF RD	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
1256 WOLF RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1266 WOLF RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1272 WOLF RD	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
1278 WOLF RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1302 WOLF RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1312 WOLF RD	N	N	U	U	Visual Inspection/Survey Response	C	C	C		N/R	N			N	
1320 WOLF RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1328 WOLF RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1336 WOLF RD	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
5818 COUNTRYSIDE LN	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
5822 COUNTRYSIDE LN	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
5826 COUNTRYSIDE LN	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
5920 COUNTRYSIDE LN	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
5938 COUNTRYSIDE LN	N	N	U	U	Visual Inspection	P	P	C		N/R	N			N	
3790 SUGAR LAKE DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
3770 SUGAR LAKE DR	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
3750 SUGAR LAKE DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
3730 SUGAR LAKE DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
3700 SUGAR LAKE DR	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
3550 SUGAR LAKE DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
3500 SUGAR LAKE DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
3270 SUGAR LAKE DR	N	N	U	U	Survey Response/Logbook/Visual Inspection	P	P	P		N/R	N			N	
3250 SUGAR LAKE DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
3200 SUGAR LAKE DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
3201 SUGAR LAKE DR	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
3251 SUGAR LAKE DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
3271 SUGAR LAKE DR	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
3291 SUGAR LAKE DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
1202 ANISE CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1200 ANISE CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
3501 SUGAR LAKE DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	

3551 SUGAR LAKE DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N
1204 CINNAMON DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
1201 CINNAMON DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
1202 CINNAMON DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N
1203 CINNAMON DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N
1200 CINNAMON DR	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N
1205 CINNAMON DR	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N
5939 COUNTRYSIDE LN	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
3701 SUGAR LAKE DR	N	N	U	U	Visual Inspection/Survey Response	C	C	C		N/R	N			N
3731 SUGAR LAKE DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
3751 SUGAR LAKE DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N
3771 SUGAR LAKE DR	N	N	U	U	Material Invoice/Survey Response/Visual Inspection	C	C	C		N/R	N			N
5945 COUNTRYSIDE LN	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
5955 COUNTRYSIDE LN	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
5963 COUNTRYSIDE LN	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
6201 COUNTRYSIDE LN	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N
6205 COUNTRYSIDE LN	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N
6668 SCHIERMEIER RD	N	N	U	U	Visual Inspection	P	p	C		N/R	N			N
6343 COUNTRYSIDE LN	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N
6355 COUNTRYSIDE LN	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N
6363 COUNTRYSIDE LN	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N
6367 COUNTRYSIDE LN	N	N	U	U	Visual Inspection/Survey Response	C	C	P		N/R	N			N
102 CEDAR LANE	N	N	U	U	Survey Response	C	C	C		N/R	N			N
104 CEDAR LANE	N	N	U	U	Construction Records	C	C	C		N/R	N			N
106 CEDAR LANE	N	N	U	U	Construction Records	C	C	C		N/R	N			N
202 CEDAR LANE	N	N	U	U	Construction Records	C	C	C		N/R	N			N
206 CEDAR LANE	N	N	U	U	Survey Response	C	C	C		N/R	N			N
210 CEDAR LANE	N	N	U	U	Construction Records	C	C	C		N/R	N			N
302 CEDAR LANE	N	N	U	U	Construction Records	C	C	P		N/R	N			N
310 CEDAR LANE	N	N	U	U	Survey Response	C	C	C		N/R	N			N
10 SPRUCE DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N
9 SPRUCE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N
8 SPRUCE DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N
7 SPRUCE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N
6 SPRUCE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N
4 SPRUCE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N
3 SPRUCE DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N
10 WESTBROOK LANE	N	N	U	U	Survey Response	C	C	C		N/R	N			N
9 WESTBROOK LANE	N	N	U	U	Construction Records	C	C	C		N/R	N			N
8 WESTBROOK LANE	N	N	U	U	Survey Response	C	C	C		N/R	N			N
7 WESTBROOK LANE	N	N	U	U	Survey Response	C	C	C		N/R	N			N
6 WESTBROOK LANE	N	N	U	U	Construction Records	C	C	C		N/R	N			N
5 WESTBROOK LANE	N	N	U	U	Construction Records	C	C	C		N/R	N			N
4 WESTBROOK LANE	N	N	U	U	Construction Records	C	C	C		N/R	N			N
3 WESTBROOK LANE	N	N	U	U	Construction Records	C	C	C		N/R	N			N
2 WESTBROOK LANE	N	N	U	U	Survey Response	C	C	C		N/R	N			N
1 SPRUCE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N
311 CEDAR LANE	N	N	U	U	Construction Records	C	C	C		N/R	N			N
707 PINE TREE LANE	N	N	U	U	Construction Records	C	C	C		N/R	N			N
709 PINE TREE LANE	N	N	U	U	Survey Response	C	C	C		N/R	N			N

711 PINE TREE LANE	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
713 PINE TREE LANE	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
715 PINE TREE LANE	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
305 PINE TREE LANE	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
207 PINE TREE LANE	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
712 PINE TREE LANE	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
710 PINE TREE LANE	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
708 PINE TREE LANE	N	Y	U	U	Survey Response	C	C	P		N/R	N			N	
209 CEDAR LANE	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
207 CEDAR LANE	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
204 PINE TREE LANE	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
205 PINE TREE LANE	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
203 PINE TREE LANE	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
201 PINE TREE LANE	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
103 PINE TREE LANE	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
101 PINE TREE LANE	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
711 KESSLER RD	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
710 KESSLER RD	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
706 KESSLER RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
708 KESSLER RD	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
101 N WEST ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
105 N WEST ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
107 N WEST ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
203 N WEST ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
207 N WEST ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
412 N WEST ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
610 W MILL ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
210 N WEST ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
310 N WEST ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
610 W PHILLIPS ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
110 N WEST ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
106 N WEST ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
612 W ST CLAIR ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
101 N POTTER ST	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
102 N POTTER ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
105 N POTTER ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
606 W PHILLIPS ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
602 W PHILLIPS ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
205 N POTTER ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
211 N POTTER ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
600 W MILL ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
300 N POTTER ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
507 W MILL ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
212 N POTTER ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
204 N POTTER ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
202 N POTTER ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
111 N WALNUT ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
570 W PHILLIPS ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
205 N WALNUT ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
207 N WALNUT ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
204 N WALNUT ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
210 N WALNUT ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
208 N WALNUT ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
211 N WALNUT ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
512 W TEMPLE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	

560 W PHILLIPS ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
108 N WALNUT ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
106 N WALNUT ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
104 N WALNUT ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
102 N WALNUT ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
408 W ST CLAIR ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
506 W ST CLAIR ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
6 N WALNUT ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
5 N WALNUT ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
3 N WALNUT ST	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
3 HARRIS CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
5 HARRIS CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
7 HARRIS CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
9 HARRIS CT	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
11 HARRIS CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
13 HARRIS CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
15 HARRIS CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
16 HARRIS CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
14 HARRIS CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
12 HARRIS CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
10 HARRIS CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8 HARRIS CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
6 HARRIS CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
4 HARRIS CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
2 HARRIS CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
2 S WALNUT ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1 CARDINAL CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
3 CARDINAL CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
5 CARDINAL CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
7 CARDINAL CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
9 CARDINAL CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
11 CARDINAL CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
111 S WALNUT ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
12 S WALNUT ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
202 S WALNUT ST	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
204 S WALNUT ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
208 S WALNUT ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
520 W APPLE ST	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
211 S WALNUT ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
205 S WALNUT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
502 W APPLE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
203 S WALNUT ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
201 S WALNUT ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
412 W HIGH ST	N	N	U	U	Visual Inspection	O	O	O		N/R	N			N	
412 W HIGH ST	N	N	U	U	Visual Inspection	O	O	O		N/R	N			N	
2 S RAILROAD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
407 W HIGH ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
502 W WHITE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8 N RAILROAD ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
10 N RAILROAD ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	

7 N MAIN ST	N	N	U	U	Visual Inspection/Visual Inspection/Survey Response	C	C	C		N/R	N			N
9 N MAIN ST	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C		N/R	N			N
15 N MAIN ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N
507 W ST CLAIR	N	N	U	U	Visual Inspection	C	C	GRR	Y	N/R	N			N
508 W ST CLAIR ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N
103 N MAIN ST A	N	N	U	U	Visual Inspection	GRR	GRR	P	Y	N/R	N			N
103 N MAIN ST B	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N
103 N MAIN ST C	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N
103 N MAIN ST D	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N
105 N MAIN ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N
107 N MAIN ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N
111 N MAIN ST	N	N	U	U	Visual Inspection	C	C	GRR	Y	N/R	N			N
202 N RAILROAD ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N
204 N RAILROAD ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N
208 N RAILROAD ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N
210 N RAILROAD ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N
212 N RAILROAD ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N
201 N MAIN ST	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C		N/R	N			N
205 N MAIN ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
209 N MAIN ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
302 N RAILROAD ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N
304 N RAILROAD ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N
306 N RAILROAD ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N
308 N RAILROAD ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N
310 N RAILROAD ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N
312 N RAILROAD ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N
301 N MAIN ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N
303 N MAIN ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N
311 N MAIN ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N
412 W TEMPLE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N
406 N RAILROAD	N	N	U	U	Survey Response	C	C	P		N/R	N			N
408 N RAILROAD ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N
412 N RAILROAD ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N
401 N MAIN ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N
407 N MAIN ST	N	N	U	U	Survey Response	C	C	GRR	Y	N/R	N			N
509 N MAIN ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N
511 N MAIN ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N
513 N MAIN ST	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N
515 N MAIN ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N
518 N MAIN ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N
601 N MAIN ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N
603 N MAIN ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N
607 N MAIN ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N
609 N MAIN ST	N	N	U	U	Construction Records	C	C	P		N/R	N			N
613 N MAIN ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N
615 N MAIN ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N
619 N MAIN ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N
621 N MAIN ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N
606 N MAIN ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N
600 N MAIN ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N
516 N MAIN ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N
514 N MAIN ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N
512 N MAIN ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N

510 N MAIN ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
506 N MAIN ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
502 N MAIN ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
500 N MAIN ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
412 N MAIN ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
408 N MAIN ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
406 N MAIN ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
402 N MAIN ST	N	N	U	U	Construction Records	C	C	C		N/R	Y	2/29/2024	C	N	
310 N MAIN ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
306 N MAIN ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
302 N MAIN ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
214 N MAIN ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
210 N MAIN ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
206 N MAIN ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
204 N MAIN ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
312 W PHILLIPS ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
308 W PHILLIPS ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
309 W PHILLIPS ST	N	N	U	U	Visual Inspection/Visual Inspection	C	C	P		N/R	N			N	
311 W PHILLIPS APT A	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
311 W PHILLIPS ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
114 N MAIN ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
112 N MAIN ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
110 N MAIN ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
106 N MAIN ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
11 N RICHLAND ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
7 N RICHLAND ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
5 N RICHLAND ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
3 N RICHLAND ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
2 S RICHLAND APT 2	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
2 S RICHLAND APT 1	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
2 S RICHLAND	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
10 S RICHLAND ST	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C		N/R	N			N	
12 S RICHLAND ST	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
102 S RICHLAND ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
106 S RICHLAND ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
108 S RICHLAND ST	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
110 S RICHLAND ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
400 W WASHINGTON ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
407 W WASHINGTON ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
409 W WASHINGTON APT A	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
409 W WASHINGTON APT B	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
409 W WASHINGTON APT C	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
409 W WASHINGTON APT D	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
409 W WASHINGTON APT E	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
409 W WASHINGTON APT F	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
409 W WASHINGTON APT G	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
409 W WASHINGTON APT H	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
401 W WASHINGTON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
206 S RICHLAND ST	Y	N	U	U	Survey Response	C	C	C		N/R	N			N	
308 W APPLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
203 S RICHLAND ST	Y	N	U	U	Survey Response	C	C	C		N/R	N			N	
309 W WASHINGTON ST	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C		N/R	N			N	
312 W WASHINGTON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
107 S RICHLAND ST	N	N	U	U	Visual Inspection	P	P	P		N/R	N			N	

109 S RICHLAND ST	N	N	U	U	Visual Inspection	P	P	P		N/R	N			N
11 S RICHLAND ST	N	N	U	U	Visual Inspection	C	C	GRR	Y	N/R	N			N
9 S RICHLAND ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N
7 S RICHLAND ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
6 S RICHLAND ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N
8 S RICHLAND ST	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N
1 S RICHLAND ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
312 W WHITE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
6 N RICHLAND ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
10 N RICHLAND ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
807 N STATE ST	N	N	U	U	Visual Inspection	P	P	C		N/R	N			N
697 N STATE STREET	N	N	U	U	Survey Response	C	C	C		N/R	N			N
701 N STATE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N
703 N STATE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N
705 N STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
711 N STATE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N
708 ROGERS DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
710 ROGERS DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
712 ROGERS DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
707 ROGERS DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
709 ROGERS DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N
713 ROGERS DR	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N
711 ROGERS DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N
715 ROGERS DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N
805 N STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
1191 N STATE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
3814 OLD FREEBURG RD	N	N	U	U	Visual Inspection	P	P	P		N/R	N			N
3695 OLD FREEBURG ROAD	N	N	U	U	Survey Response/Visual Inspection	P	P	P		N/R	N			N
3613 OLD FREEBURG ROAD	N	N	U	U	Visual Inspection	P	P	C		N/R	N			N
3569 OLD FREEBURG ROAD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
3549 OLD FREEBURG ROAD	N	N	U	U	Visual Inspection	P	P	C		N/R	N			N
3543 OLD FREEBURG RD	N	N	U	U	Visual Inspection	P	P	C		N/R	N			N
3537 OLD FREEBURG ROAD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
3531 OLD FREEBURG ROAD	N	N	U	U	Visual Inspection	P	P	C		N/R	N			N
2 SCHMITTLING LN	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
1200 N STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
1050 N STATE ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N
1000 N STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
1 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
2 DEERFIELD CT	N	N	U	U	Survey Response	C	C	C		N/R	N			N
3 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
4 DEERFIELD CT	N	N	U	U	Survey Response	C	C	P		N/R	N			N
5 DEERFIELD CT	N	N	U	U	Survey Response	C	C	P		N/R	N			N
6 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
7 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
8 DEERFIELD CT	N	N	U	U	Survey Response	C	C	P		N/R	N			N
9 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
10 DEERFIELD CT	N	N	U	U	Survey Response	C	C	C		N/R	N			N
11 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
12 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
13 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
14 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
15 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
16 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N



72 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
73 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
74 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
75 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
76 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
77 DEERFIELD CT	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
78 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
79 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
80 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
81 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
82 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
83 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
84 DEERFIELD CT	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
85 DEERFIELD CT	N	Y	U	U	Visual Inspection/Survey Response	C	C	P		N/R	N			N	
86 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
87 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
88 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
89 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
90 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
91 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
92 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
93 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
94 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
95 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
96 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
97 DEERFIELD CT	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
98 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
99 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
100 DEERFIELD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1 SCHMITTLING LANE	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
200 WUEST LN	Y	N	U	U	Visual Inspection/Survey Response	P	P	P		N/R	N			N	
700A N STATE	N	N	U	U	Survey Response	O	O	P		N/R	N			N	
700E N STATE ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
700F N STATE ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
702 N STATE ST, APT A	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
702 N STATE ST, APT B	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
702 N STATE ST, APT C	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
702 N STATE ST, APT D	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
702 N STATE ST, APT E	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
702 N STATE ST, APT F	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
702 N STATE ST, APT G	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
702 N STATE ST, APT H	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
901 MEADOW BROOK DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
905 MEADOW BROOK DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
907 MEADOW BROOK DR	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
911 MEADOW BROOK DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
913 MEADOW BROOK DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
915 MEADOW BROOK DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
301 E MEADOW BROOK DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
303 E MEADOW BROOK DR	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
305 E MEADOW BROOK DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
307 E MEADOW BROOK DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	

309 E MEADOW BROOK DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
311 E MEADOW BROOK DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
313 E MEADOW BROOK DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
312 E MEADOW BROOK DR	N	N	U	U	Visual Inspection/Survey Response	C	C	C		N/R	N			N	
913 DEER TRAIL CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
911 DEER TRAIL CT	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
909 DEER TRAIL CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
906 DEER TRAIL CT	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
908 DEER TRAIL CT	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
910 DEER TRAIL CT	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
306 E MEADOW BROOK DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
302 E MEADOW BROOK DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
909 LAKE TRAIL CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
906 LAKE TRAIL CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
912 MEADOW BROOK DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
906 MEADOW BROOK DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
902 MEADOW BROOK DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
312 LAKE POINTE CT	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
308 LAKE POINTE CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
304 LAKE POINTE CT	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
300 LAKE POINTE CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
612 N STATE ST	Y	N	U	U		C	C	C		N/R	N			N	
620 N STATE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
705 MEADOW BROOK DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
707 MEADOW BROOK DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
709 MEADOW BROOK DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
713 MEADOW BROOK DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
717 MEADOW BROOK DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
721 MEADOW BROOK DR	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
725 MEADOW BROOK DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
803 MEADOW BROOK DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
301 DOGWOOD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
722 MEADOW BROOK DR	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
718 MEADOW BROOK DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
714 MEADOW BROOK DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
710 MEADOW BROOK DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
706 MEADOW BROOK DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
708 MEADOW BROOK DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
701 OAK BROOK DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
703 OAK BROOK DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
705 OAK BROOK DR	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
711 OAK BROOK DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
715 OAK BROOK DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
719 OAK BROOK DR	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
723 OAK BROOK DR	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
305 DOGWOOD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
309 DOGWOOD CT	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	

313 DOGWOOD CT	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
317 DOGWOOD CT	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
316 DOGWOOD CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
720 OAK BROOK DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
716 OAK BROOK DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
712 OAK BROOK DR	N	N	U	U	Visual Inspection/Survey Response	C	C	C		N/R	N			N	
708 OAK BROOK DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
618 RED OAK DR	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
614 RED OAK DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
610 RED OAK DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
606 RED OAK DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
602 RED OAK DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
603 BROOK STONE CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
607 BROOK STONE CT	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
611 BROOK STONE CT	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
615 BROOK STONE CT	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
619 BROOK STONE CT	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
623 BROOK STONE CT	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
627 BROOK STONE CT	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
624 BROOK STONE CT	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
620 BROOK STONE CT	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
612 BROOK STONE CT	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
608 BROOK STONE CT	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
604 BROOK STONE CT	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
600 BROOK STONE CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
346 MEADOW RIDGE DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
348 MEADOW RIDGE DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
356 MEADOW RIDGE DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
601 MEADOW LAKE DR	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
605 MEADOW LAKE DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
607 MEADOW LAKE DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
613 MEADOW LAKE DR	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
617 MEADOW LAKE DR	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
621 MEADOW LAKE DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
625 MEADOW LAKE DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
629 MEADOW LAKE DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
630 MEADOW LAKE DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
628 MEADOW LAKE DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
624 MEADOW LAKE DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
618 MEADOW LAKE DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
610 MEADOW LAKE DR	N	N	U	U	Visual Inspection/Survey Response	C	C	P		N/R	N			N	
409 ROSA LN	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
604 N STATE ST	N	N	U	U	Survey Response	P	P	P		N/R	N			N	
517 N STATE ST	N	N	U	U	Visual Inspection	P	P	P		N/R	N			N	
519 N STATE ST	N	N	U	U	Survey Response	P	P	C		N/R	N			N	

212 S MONROE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
301 W WASHINGTON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
302 W WASHINGTON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
106 S MONROE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
102 S MONROE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
14 S MONROE ST	Y	N	U	U	Survey Response	C	C	C		N/R	N			N	
10 S MONROE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
6 S MONROE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1 N MONROE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
9 N MONROE ST	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
11 N MONROE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
308 W ST CLAIR ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
302 W ST CLAIR ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
301 W PHILLIPS ST	N	N	U	U	Visual Inspection	C	C	GRR	Y	N/R	N			N	
305 W PHILLIPS ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
203 N MONROE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
301 W MILL ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
207 N MONROE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
305 W MILL ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
301 N DEWEY ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
305 N DEWEY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
309 N DEWEY ST	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
401 N DEWEY ST	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
411 N DEWEY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
501 N DEWEY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
503 N DEWEY ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
506 N DEWEY ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
508 N DEWEY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
204 W KOESTERER ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
412 N DEWEY ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
406 N DEWEY ST	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
312 W TEMPLE	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
310 N DEWEY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
306 N DEWEY ST	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
302 N DEWEY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
210 N MONROE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
208 N MONROE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
206 N MONROE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
202 N MONROE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
114 N MONROE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
110 N MONROE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
104 N MONROE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
212 W ST CLAIR ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
12 N MONROE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8 N MONROE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
209 W HIGH ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
311 W HIGH ST	N	N	U	U	Visual Inspection	P	P	P		N/R	N			N	
313 W HIGH ST	N	N	U	U	Visual Inspection	P	P	P		N/R	N			N	
105 S MONROE ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
107 S MONROE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
111 S MONROE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
201 S MONROE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
208 W APPLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
206 W APPLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	

212 S BELLEVILLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
201 W WASHINGTON ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
110 S BELLEVILLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
112 S BELLEVILLE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
108 S BELLEVILLE ST	N	N	U	U	Visual Inspection	C	C	GRR	Y	N/R	N			N	
106 S BELLEVILLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
201 A W HIGH ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
201 B W HIGH ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
102 A S BELLEVILLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
102 B S BELLEVILLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
205 W HIGH ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
109 N BELLEVILLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
203 N BELLEVILLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
205 N BELLEVILLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
211 N BELLEVILLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
201 W MILL ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
202 W MILL ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
305 N MONROE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
309 N MONROE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
401 N MONROE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
407 N MONROE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
411 N MONROE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
501 N MONROE ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
505 N MONROE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
511 N MONROE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
410 N MONROE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
406 N MONROE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
404 N MONROE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
402 N MONROE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
208 W TEMPLE ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
312 N MONROE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
310 N MONROE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
308 N MONROE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
306 N MONROE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
302 N MONROE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
210 N BELLEVILLE ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
208 N BELLEVILLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
206 N BELLEVILLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
112 W PHILLIPS ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
111 W PHILLIPS ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
108 N BELLEVILLE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
106 N BELLEVILLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
112 W ST CLAIR ST	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
8 N BELLEVILLE ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
2 N BELLEVILLE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
1 S BELLEVILLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
9 S BELLEVILLE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
13 S BELLEVILLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
101 S BELLEVILLE ST	N	N	U	U	Logbook	C	C	C		N/R	Y	2018	C	N	
105 S BELLEVILLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
107 S BELLEVILLE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
110 W WASHINGTON ST	N	N	U	U	Visual Inspection	P	P	P		N/R	N			N	
105 W WASHINGTON ST	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C		N/R	N			N	
111 W WASHINGTON ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	

111 A W WASHINGTON ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
112 W APPLE ST	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C		N/R	N			N	
108 W APPLE ST	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C		N/R	N			N	
305 S BELLEVILLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
307 S BELLEVILLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
309 S BELLEVILLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
311 S BELLEVILLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
313 S BELLEVILLE ST	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
315 S BELLEVILLE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
308 S ALTON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
11 W APPLE ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
101 W APPLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
103 W APPLE ST	N	N	U	U	Survey Response	C	C	GRR	Y	N/R	N			N	
106 W APPLE ST	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
102 W APPLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
101 W WASHINGTON ST	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C		N/R	N			N	
103 W WASHINGTON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
106 W WASHINGTON ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
120 S ALTON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
110 S ALTON ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
106 S ALTON ST	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C		N/R	N			N	
104 S ALTON ST	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C		N/R	N			N	
102 S ALTON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
105 W HIGH ST	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C		N/R	N			N	
10 S ALTON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
10 S ALTON SUITE 1	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
10 S ALTON SUITE 2	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
102 W HIGH ST APT A	N	N	U	U	Visual Inspection	P	P	P		N/R	N			N	
102 W HIGH ST APT B	N	N	U	U	Visual Inspection	P	P	P		N/R	N			N	
102 W HIGH ST APT C	N	N	U	U	Visual Inspection	P	P	P		N/R	N			N	
102 W HIGH ST APT D	N	N	U	U	Visual Inspection	P	P	P		N/R	N			N	
8 S ALTON ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
6 S ALTON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
5 S ALTON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
4 S ALTON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
2 S ALTON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
101 N ALTON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
105 N ALTON ST	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
109 N ALTON ST	N	N	U	U	Survey Response	C	C	GRR	Y	N/R	N			N	
203 N ALTON ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
207 N ALTON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
209 N ALTON ST	N	Y	U	U	Visual Inspection	C	C	C		N/R	N			N	
301 N ALTON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
305 N ALTON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
307 N ALTON ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
309 N ALTON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
311 N ALTON ST	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
405 N ALTON ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
411 N ALTON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
501 N STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
9 W KOESTERER ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
408 N ALTON ST APT D	N	N	U	U	Survey Response	C	C	C		N/R	N			N	

408 N ALTON ST APT C	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
408 N ALTON ST APT B	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
408 N ALTON ST APT A	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
402 N ALTON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
312 N ALTON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
308 N ALTON ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
302 N ALTON ST	N	N	U	U	Visual Inspection	C	C	GRR		N/R	N			N	
212 N ALTON ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
208 N ALTON ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
206 N ALTON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
202 N ALTON ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
104 N ALTON ST	N	N	U	U	Survey Response/Material Invoice	C	C	P		N/R	N			N	
106 N ALTON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
108 N ALTON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
110 N ALTON ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
10 N ALTON	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
11 S ALTON ST	Y	Y	U	U	Visual Inspection	C	C	P		N/R	N			N	
7 W HIGH ST	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
103 S ALTON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
105 S ALTON ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
107 S ALTON ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
10 W WASHINGTON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
12 W WASHINGTON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
5 W WASHINGTON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
201 S ALTON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
12 W APPLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
411 N STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
405 N STATE ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
401 N STATE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
311 N STATE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
307 N STATE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
301 N STATE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
211 N STATE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
203 N STATE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
201 N STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
105 N STATE	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
105 N STATE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
103 N STATE ST	N	N	U	U	Survey Response	P	P	P		N/R	N			N	
103 N STATE	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
2 S STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
4 S STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8 S STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
2 W HIGH ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1 W HIGH ST	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C		N/R	N			N	
302 S STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
306 S STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
310 S STATE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
312 S STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
406 S STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
410 S STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
502 S STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
506 S STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
508 S STATE ST	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C		N/R	N			N	

1 LINCOLN COURT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
600 S STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
830 S STATE ST	Y	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
840 S STATE	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
850 S STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
4 HILL MINE RD	Y	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
351 HILL MINE RD	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
1032 S STATE ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
1109 S STATE ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
1215 S STATE ST	N	N	2/18/2022	2022	Survey Response/Logbook/Visual Inspection	C	C	P		N/R	N			N	
1230 S STATE ST	N	N	U	U	Construction Records	C	C	P		N/R	N			N	
1248 S STATE ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
7576 PRESS ROAD	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
1 COMMERCE DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
18 COMMERCE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
17 COMMERCE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
10 SOUTHGATE DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
20 SOUTHGATE DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
30 SOUTHGATE DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
32 SOUTHGATE DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
100 SOUTHGATE DR	N	N	U	U	Construction Records	C	C	P		N/R	N			N	
102 SOUTHGATE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
110 SOUTHGATE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
112 SOUTHGATE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
120 SOUTHGATE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
122 SOUTHGATE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
200 SOUTHGATE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
202 SOUTHGATE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
210 SOUTHGATE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
212 SOUTHGATE DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
220 SOUTHGATE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
223 SOUTHGATE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
221 SOUTHGATE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
300 SOUTHGATE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
302 SOUTHGATE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
304 SOUTHGATE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
306 SOUTHGATE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
308 SOUTHGATE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
310 SOUTHGATE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
332 SOUTHGATE APT 1	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
332 SOUTHGATE APT 2	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
332 SOUTHGATE APT 3	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
332 SOUTHGATE APT 4	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
330 SOUTHGATE APT 5	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
330 SOUTHGATE APT 6	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
330 SOUTHGATE APT 7	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
330 SOUTHGATE APT 8	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
853 SOUTHGATE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
851 SOUTHGATE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
843 SOUTHGATE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
841 SOUTHGATE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
801 SOUTHGATE APT 1	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
801 SOUTHGATE APT 2	N	N	U	U	Survey Response	C	C	C		N/R	N			N	

801 SOUTHGATE APT 3	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
801 SOUTHGATE APT 4	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
803 SOUTHGATE APT 5	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
803 SOUTHGATE APT 6	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
803 SOUTHGATE APT 7	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
803 SOUTHGATE APT 8	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
820 SOUTHGATE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
840 SOUTHGATE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
842 SOUTHGATE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
309 SOUTHGATE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
307 SOUTHGATE DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
305 SOUTHGATE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
303 SOUTHGATE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
301 SOUTHGATE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
213 SOUTHGATE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
211 SOUTHGATE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
203 SOUTHGATE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
201 SOUTHGATE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
123 SOUTHGATE DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
121 SOUTHGATE DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
111 SOUTHGATE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
605 S STATE ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
603 S STATE ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
601 S STATE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
515 S EDISON ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
511 S EDISON ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
111 E SOUTH ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
112 E SOUTH ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
506 S EDISON ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
511 S STATE ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
507 S STATE ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
505 S STATE ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
503 S STATE ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
501 S STATE ST	N	N	U	U	Survey Response	C	C	GRR	Y	N/R	N			N	
106 E HILL ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
107 E HILL ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
403 S STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
106 E EMILY ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
108 E EMILY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
110 E EMILY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
112 E EMILY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
107 E EMILY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
105 E EMILY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
101 E EMILY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
104 E APPLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
106 E APPLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
108 E APPLE ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
109 E APPLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
105 E APPLE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
101 E APPLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
211 S STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
205 S STATE ST	Y	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
203 S STATE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
111 S STATE ST A	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C		N/R	N			N	

111 S STATE ST B	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C		N/R	N			N	
111 S STATE ST C	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C		N/R	N			N	
115 S STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
117 S STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
107 S STATE	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
105 A S STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
101 S STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
11 S STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
4 E WHITE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
2 N STATE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
4 N STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
6 N STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
12 N STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
102 N STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
106 N STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
108 N STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
110 N STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
112 N STATE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
202 N STATE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
206 N STATE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
208 N STATE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
212 N STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
302 N STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
304 N STATE ST	N	N	U	U	Visual Inspection	P	P	P		N/R	N			N	
308 N STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
312 N STATE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
402 N STATE ST	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
409 N EDISON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
405 N EDISON ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
401 N EDISON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
311 N EDISON ST	N	N	U	U	Visual Inspection	C	C	GRR	Y	N/R	N			N	
307 N EDISON ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
301 N EDISON ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
211 N EDISON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
207 N EDISON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
203 N EDISON ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
201 N EDISON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
111 N EDISON ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
107 N EDISON ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
105 N EDISON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
11 E ST CLAIR ST	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
9 N EDISON ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
5 N EDISON ST	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
3 N EDISON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
11 E WHITE ST	N	N	U	U	Survey Response	C	C	GRR	Y	N/R	N			N	
12 E WHITE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
6 S EDISON ST	N	N	U	U	Visual Inspection/Visual Inspection	C	C	P		N/R	N			N	
10 S EDISON ST	N	N	U	U	Visual Inspection/Visual Inspection	C	C	GRR	Y	N/R	N			N	
11 E HIGH ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
102 S EDISON ST	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
P	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
11 E WASHINGTON ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	

8 E WASHINGTON ST	N	N	U	U	Visual Inspection/Visual Inspection	C	C	GRR		N/R	N			N	
10 E WASHINGTON ST	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C		N/R	N			N	
113 E APPLE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
113 E APPLE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
112 E APPLE ST	N	N	U	U	Survey Response	GRR	GRR	GRR	Y	N/R	N			N	
114 E APPLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
308 S CHERRY ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
310 S CHERRY ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
109 E EMILY ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
114 E EMILY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
116 E EMILY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
406 S CHERRY ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
117 E HILL ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
113 E HILL ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
109 E HILL ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
112 E HILL ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
114 E HILL ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
116 E HILL ST	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
201 E HILL ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
202 E HILL ST	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
205 E HILL ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
206 E HILL ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
209 E HILL ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
410 S VINE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
303 E HILL ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
401 S VINE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
210 E EMILY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
118 E EMILY	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
304 S VINE ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
205 E EMILY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
206 E EMILY ST	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
202 E EMILY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
311 S CHERRY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
202 E APPLE ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
204 E APPLE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
206 E APPLE ST	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C		N/R	N			N	
100 E WASHINGTON ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
109 S EDISON ST	N	N	U	U	Visual Inspection/Visual Inspection	C	C	GRR		N/R	N			N	
107 S EDISON ST	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C		N/R	N			N	
105 S EDISON ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
101 S EDISON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
101 E HIGH ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
7 S EDISON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
5 S EDISON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
101 E WHITE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
6 N EDISON	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8 N EDISON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
10 N EDISON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
101 E ST CLAIR ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
104 N EDISON ST	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
108 N EDISON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
110 N EDISON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	

112 N EDISON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
202 N EDISON ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
208 N EDISON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
212 N EDISON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
302 N EDISON ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
306 N EDISON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
310 N EDISON ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
101 E TEMPLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
410 N EDISON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
502 N EDISON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
409 N CHERRY ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
407 N CHERRY ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
405 N CHERRY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
109 E TEMPLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
110 E TEMPLE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
305 N CHERRY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
301R N CHERRY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
301 N CHERRY ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
211 N CHERRY ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
207 N CHERRY ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
203 N CHERRY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
201 N CHERRY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
111 N CHERRY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
111 E ST CLAIR ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
7 N CHERRY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
111 E WHITE ST	N	N	U	U	Visual Inspection	C	C	GRR	Y	N/R	N			N	
2 S CHERRY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8 S CHERRY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
12 S CHERRY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
112 E HIGH ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
106 S CHERRY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
108 S CHERRY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
111 E WASHINGTON ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
202 S CHERRY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
204 S CHERRY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
208 S CHERRY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
211 S CHERRY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
201 S CHERRY ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
107 S CHERRY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
105 S CHERRY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
201 E HIGH ST	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
7 S CHERRY ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
201 E WHITE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
200 E WHITE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
4 N CHERRY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8 N CHERRY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
12 N CHERRY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
102 N CHERRY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
106 N CHERRY ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
112 N CHERRY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
202 N CHERRY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
204 N CHERRY ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
206 N CHERRY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
210 N CHERRY ST	N	N	U	U	Survey Response	C	C	GRR	Y	N/R	N			N	

200 E MILL ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
201 E MILL ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
202 E TEMPLE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
201 E TEMPLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
412 N CHERRY ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
411 N VINE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
410 N VINE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
411 N PITTS ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
414 N PITTS ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
412 N PITTS ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
401 E TEMPLE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
504 N PITTS ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
403 E TEMPLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
407 E TEMPLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
406 E TEMPLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
402 E TEMPLE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
400 E TEMPLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
307 E TEMPLE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
305 E TEMPLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
303 E TEMPLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
408 N VINE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
211 E TEMPLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
209 E TEMPLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
203 E TEMPLE ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
206 E TEMPLE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
208 E TEMPLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
300 E TEMPLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
306 E TEMPLE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
308 E TEMPLE ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
307 E MILL ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
305 E MILL ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
303 E MILL ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
301 E MILL ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
211 E MILL ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
209 E MILL ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
207 E MILL ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
205 E MILL ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
401 E MILL ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
405 E MILL ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
407 E MILL ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
409 E MILL ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
411 E MILL ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
7619 JACKS RUN RD	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
7606 JACKS RUN RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
422 E MILL ST	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
501 E MILL ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
412 E MILL ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
414 E MILL ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
400 E MILL ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
318 A E MILL ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
318 B E MILL ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
306 E MILL ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
212 N VINE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
211 N VINE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
201 N VINE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	

111 N VINE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
105 N VINE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
101 N VINE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
202 E ST CLAIR ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
7 N VINE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
5 N VINE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
3 N VINE ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
6 S VINE ST	N	N	2021	U	Logbook/Survey Response	P	P	P		N/R	N			N	
8 S VINE ST	N	N	U	U	Survey Response	C	C	GRR	Y	N/R	N			N	
10 S VINE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
205 E HIGH ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
102 S VINE ST	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
104 S VINE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
106 S VINE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
108 S VINE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
112 S VINE ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
202 S VINE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
206 S VINE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
210 S VINE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
207 E APPLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
300 S VINE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
301 S VINE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
302 S VINE ST	N	N	U	U	Visual Inspection	C	C	GRR	Y	N/R	N			N	
211 S VINE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
205 S VINE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
302 E WASHINGTON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
111 S VINE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
105 S VINE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
101 S VINE ST	N	N	U	U	Visual Inspection	C	C	C	Y	6/5/2023	Y	6/5/2023	C	N	
301 E HIGH ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
5 S VINE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
1 S VINE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
6 N VINE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
102 N VINE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
108 N VINE ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
110 N VINE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
112 N VINE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
302 ST CLAIR CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
304 ST CLAIR CT	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
306 ST CLAIR CT	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
308 E ST CLAIR CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
313 ST CLAIR CT	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
311 ST CLAIR CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
309 ST CLAIR CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
307 ST CLAIR CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
314 ST CLAIR CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
312 ST CLAIR CT	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
305 E HIGH ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
307 E HIGH ST	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
313 E HIGH ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
415 E HIGH ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
405 E HIGH ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
401 E HIGH ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
101 S PITTS ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	

312 E HIGH ST	N	N	U	U	Visual Inspection	C	C	C		N/R	Y	2/22/2021	C	N	
106 S PITTS ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
112 S PITTS ST	N	N	U	U	Survey Response	C	C	GRR	Y	N/R	N			N	
105 S PITTS ST	N	N	U	U	Visual Inspection/Visual Inspection	C	C	C		N/R	N			N	
111 S PITTS ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
312 E WASHINGTON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
206 S PITTS ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
212 S PITTS ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
301 S PITTS ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
303 S PITTS ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
407 CEMETERY ROAD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
417 CEMETERY ROAD	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
455 CEMETERY ROAD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
2 PALOMAR LAKE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
5 PALOMAR LAKE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
7 PALOMAR LAKE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
13 PALOMAR LAKE DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
519 CEMETERY RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
537 CEMETERY RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
601 HENDERSON POINTE TR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
541 CEMETERY RD	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
545 CEMETERY RD	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
549 CEMETERY RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
605 HENDERSON POINTE TR	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
609 HENDERSON POINTE TR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
755 CEMETERY ROAD	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
613 HENDERSON POINTE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
548 CEMETERY RD	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
PARK METER	Y	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
310 E HILL - SWIM POOL	Y	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
311 OLD FAYETTEVILLE	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
601 ADELE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
609 ADELE ST	N	N	U	U	Survey Response	C	C	O		N/R	N			N	
410 SILVER ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
611 ADELE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
405 FIRST ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1 MILFORD APT A	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1 MILFORD APT B	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1 MILFORD APT C	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1 MILFORD APT D	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
2 MILFORD DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
3 MILFORD DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
4 MILFORD DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
5 A MILFORD DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
5 B MILFORD DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
6 MILFORD DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
7 MILFORD DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8 MILFORD DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
9 MILFORD DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
10 B MILFORD DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
10A MILFORD DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
11 MILFORD DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
351 URBANNA DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
331 URBANNA DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	

301 URBANNA DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
271 URBANNA DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
251 URBANNA DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
201 URBANNA DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
171 URBANNA DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
151 URBANNA DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
611 ELIZABETH DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
100 ELIZABETH DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
101 ELIZABETH DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
103 ELIZABETH DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
105 ELIZABETH DR	N	N	U	U	Construction Records	C	C	GRR	Y	N/R	N			N	
107 ELIZABETH DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
203 ELIZABETH DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
605 CATHERINE CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
607 CATHERINE CT	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
608 CATHERINE CT	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
205 ELIZABETH DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
606 CATHERINE CT	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
607 PHIL-KATE CIRCLE	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
207 ELIZABETH DR	N	N	U	U	Construction Records	C	C	P		N/R	N			N	
605 PHIL-KATE CIRCLE	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
606 PHIL-KATE CIRCLE	N	N	U	U	Construction Records	C	C	P		N/R	N			N	
608 PHIL-KATE CIRCLE	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
610 PHIL-KATE CIRCLE	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
202 ELIZABETH DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
204 ELIZABETH DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
206 ELIZABETH DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
208 ELIZABETH DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
300 ELIZABETH DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
302 ELIZABETH DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
304 ELIZABETH DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
306 ELIZABETH DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
303 ELIZABETH DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
305 ELIZABETH DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
610 ADELE ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
608 ADELE ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
600 ADELE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
316 OLD FAYETTEVILLE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
312 OLD FAYETTEVILLE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
310 OLD FAYETTEVILLE	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
12 MEYER DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
13 MEYER DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
14 MEYER DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
15 MEYER DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
16 MEYER DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
17 MEYER DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
18 MEYER DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
19 MEYER DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
20 MEYER DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
21 MEYER DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
22 MEYER DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
23 MEYER DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
24 MEYER DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
395 OLD FAYETTEVILLE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
2 PARK ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	

4 PARK ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
6 PARK ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
8 PARK ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
10 PARK ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
12 PARK ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
14 PARK ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
13 PARK ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
11 PARK ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
9 PARK ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
7 PARK ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
5 PARK ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
3 PARK ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
1 PARK ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
415 OLD FAYETTEVILLE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
425 OLD FAYETTEVILLE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
630 DINTELMANN	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
600 DINTELMANN LN	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
700 KRISTIE LYNN ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
702 KRISTIE LYNN ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
11 WOODVIEW DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
710 KRISTIE LYNN ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
708 KRISTIE LYNN ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
704 KRISTIE LYNN ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
714 KRISTIE LYNN ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
715 KRISTIE LYNN ST	N	N	U	U	Construction Records/Survey Response	C	C	C		N/R	N			N	
713 KRISTIE LYNN ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
711 KRISTIE LYNN ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
709 KRISTIE LYNN ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
712 KRISTIE LYNN ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
10 WOODVIEW DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
703 KRISTIE LYNN ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
707 KRISTIE LYNN ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
706 KRISTIE LYNN ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
701 KRISTIE LYNN ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
705 KRISTIE LYNN ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
700 MARY ANN CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
702 MARY ANN CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
704 MARY ANN CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
706 MARY ANN CT	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
9 WOODVIEW DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
708 MARY ANN CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
710 MARY ANN CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
712 MARY ANN CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
714 MARY ANN CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
715 MARY ANN CT	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
713 MARY ANN CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
711 MARY ANN CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
709 MARY ANN CT	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
707 MARY ANN CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
7 WOODVIEW DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
705 MARY ANN CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
703 MARY ANN CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
701 MARY ANN CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
708 SAXONY LN	N	N	U	U	Survey Response	C	C	C		N/R	N			N	

809 SAXONY LN	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
709 SAXONY LN	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
808 SAXONY LN	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
8 WOODVIEW DR	N	N	11/16/2021	U	Survey Response/Logbook/Visual Inspection	C	C	C		N/R	N			N	
2 COUNTRY LANE	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
4 Country Lane	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
5 COUNTRY LANE	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
3 COUNTRY LANE	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
1 COUNTRY LANE	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
505 OLD FAYETTEVILLE	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
1 EDGEWOOD CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
2 EDGEWOOD CT	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
3 EDGEWOOD CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
4 EDGEWOOD CT	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
5 EDGEWOOD CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
6 EDGEWOOD CT	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
7 EDGEWOOD CT	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
8 EDGEWOOD CT	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
9 EDGEWOOD CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
10 EDGEWOOD CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
400 BRICK LN	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
500 BRICK LN	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
11 EDGEWOOD CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
12 EDGEWOOD CT	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
13 EDGEWOOD CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
14 EDGEWOOD CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
15 EDGEWOOD CT	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
1 LAKEVIEW DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
3 LAKEVIEW DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
7 LAKEVIEW DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
9 LAKEVIEW DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
11 LAKEVIEW DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
13 LAKEVIEW DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
15 LAKEVIEW DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
17 LAKEVIEW DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
19 LAKEVIEW DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
21 LAKEVIEW DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
23 LAKEVIEW DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
25 LAKEVIEW DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
29 LAKEVIEW DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
27 LAKEVIEW DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
24 LAKEVIEW DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
28 LAKEVIEW DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
31 LAKEVIEW DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
33 LAKEVIEW DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
110 WILD CHERRY LN	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
568 CEMETERY ROAD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
35 LAKEVIEW DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
37 LAKEVIEW DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
32 LAKEVIEW DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
164 SUNRISE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
160 SUNRISE DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
150 SUNRISE DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
26 LAKEVIEW DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	

22 LAKEVIEW DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
20 LAKEVIEW DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
18 LAKEVIEW DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
16 LAKEVIEW DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
14 LAKEVIEW DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
12 LAKEVIEW DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
10 LAKEVIEW DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
8 LAKEVIEW DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
6 LAKEVIEW DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
7 TRITT LANE	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
4 LAKEVIEW DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
2 LAKEVIEW DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
608 OLD FAYETTEVILLE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
603 OLD FAYETTEVILLE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
611 OLD FAYETTEVILLE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
615 OLD FAYETTEVILLE	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
602 OLD FAYETTEVILLE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
604 OLD FAYETTEVILLE	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
706 JACOBS LN	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
749 OLD FAYETTEVILLE RD	N	N	3/28/2022	U	Logbook/Visual Inspection/Survey Response	C	C	P		N/R	N			N	
817 OLD FAYETTEVILLE	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
770 OLD FAYETTEVILLE RD	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
5108 WOUNDED KNEE TRAIL	N	N	U	U		C	C	P		N/R	N			N	
5149 DOVETAIL	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
830 OLD FAYETTEVILLE RD	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
3708 STATE ROUTE 15	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
3702 STATE ROUTE 15	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
3658 STATE ROUTE 15	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
755 URBANNA DR	N	N	2021	U	Survey Response/Logbook/Visual Inspection	C	C	C		N/R	N			N	
745 URBANNA DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
3 LAKE DR	N	N	U	U	Visual Inspection/Survey Response	C	C	C		N/R	N			N	
641 URBANNA DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
635 URBANNA DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
631 URBANNA DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
7 DRACO DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
5 DRACO DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
102 WILLOW DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
104 WILLOW DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
106 WILLOW DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
103 LAKE DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
110 WILLOW DR	N	N	U	U	Construction Records	C	C	P		N/R	N			N	
107 WILLOW DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
105 WILLOW DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
103 WILLOW DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
102 DRACO DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
511 DRACO DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
16 HICKORY DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
514 DRACO DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
516 DRACO DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
518 DRACO DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
509 B DRACO DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
509 A DRACO DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	

10 HICKORY DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
12 HICKORY DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
11 HICKORY DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
503 B DRACO DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
503 A DRACO DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
501 DRACO DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
508 DRACO DR	N	N	U	U	Material Invoice	C	C	C		N/R	N			N	
510 DRACO DR	N	N	U	U	Material Invoice	C	C	P		N/R	N			N	
4 FRIEDA LANE	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
5 FRIEDA LANE	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
1 CYPRESS LANE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
315 LAKE DR	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
314 LAKE DR	N	N	U	U	Visual Inspection	C	C	p		N/R	N			N	
308 LAKE DR	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
746 URBANNA DR	Y	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
746 URBANNA DR	Y	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
655 URBANNA DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
654 SOLUTIONS DR	Y	N	U	U	Survey Response	C	C	C		N/R	N			N	
640 URBANNA DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
630 URBANNA DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
620 URBANNA DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
610 URBANNA DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
502 DRACO DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
512 DRACO DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
930 CEMETERY ROAD	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
930 CEMETERY RD	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
6467 WHITE OAKS CLUB RD	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
83 BARBER LANE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
5501 BARBER LANE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
5505 BARBER LANE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8457 RIVER KING RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
100 WOODS MANOR DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
102 WOODS MANOR DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
200 WOODS MANOR DR	N	N	U	U	Construction Records	C	C	P		N/R	N			N	
202 WOODS MANOR DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
204 WOODS MANOR DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
300 WOODS MANOR DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
302 WOODS MANOR DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
304 WOODS MANOR DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
500 WOODS MANOR DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
502 WOODS MANOR DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
504 WOODS MANOR DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
507 WOODS MANOR DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
505 WOODS MANOR DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
503 WOODS MANOR DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
203 WOODS MANOR DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
500 SHADOW WOOD CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
502 SHADOW WOOD CT	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
504 SHADOW WOOD CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
506 SHADOW WOOD CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
507 SHADOW WOOD CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
505 SHADOW WOOD CT	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
503 SHADOW WOOD CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
501 SHADOW WOOD CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	

101 WOODS MANOR DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
100 FOREST RIDGE CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
102 FOREST RIDGE CT	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
103 FOREST RIDGE CT	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
101 FOREST RIDGE CT	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
510 N EDISON	N	N	U	U	Material Invoice/Survey Response	C	C	C		N/R	N			N	
512 N EDISON	N	N	U	U	Survey Response/Material Invoice	C	C	C		N/R	N			N	
514 N EDISON	N	N	U	U	Material Invoice	C	C	C		N/R	N			N	
518 N EDISON	N	N	U	U	Material Invoice	C	C	C		N/R	N			N	
520 N EDISON	N	N	U	U	Material Invoice	C	C	P		N/R	N			N	
522 N EDISON	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
526 N EDISON	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
528 N EDISON	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
530 N EDISON ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
517 N EDISON	N	N	U	U	Material Invoice	C	C	C		N/R	N			N	
519 N EDISON	N	N	U	U	Survey Response/Material Invoice	C	C	P		N/R	N			N	
521 N EDISON	N	N	U	U	Material Invoice/Survey Response	C	C	C		N/R	N			N	
525 N EDISON	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
527 N EDISON	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
529 N EDISON	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
603 N EDISON ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
605 N EDISON ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
103 TALL MAPLE CT	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
109 TALL MAPLE CT	N	N	U	U	Material Invoice/Survey Response	C	C	P		N/R	N			N	
113 TALL MAPLE COURT	N	N	U	U	Material Invoice	C	C	C		N/R	N			N	
117 TALL MAPLE COURT	N	N	U	U	Material Invoice	C	C	C		N/R	N			N	
121 TALL MAPLE CT	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
125 TALL MAPLE CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
133 TALL MAPLE COURT	N	N	U	U	Material Invoice	C	C	C		N/R	N			N	
137 TALL MAPLE COURT	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
147 TALL MAPLE CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
148 TALL MAPLE CT	N	N	U	U	Survey Response/Material Invoice	C	C	C		N/R	N			N	
144 TALL MAPLE CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
120 TALL MAPLE COURT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
116 TALL MAPLE CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
512 CREEK RIDGE CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
508 CREEK RIDGE CT	N	N	U	U	Survey Response/Material Invoice	C	C	C		N/R	N			N	
504 CREEK RIDGE CT	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
500 CREEK RIDGE CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
501 CREEK RIDGE CT	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
505 CREEK RIDGE CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
509 CREEK RIDGE CT	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
513 CREEK RIDGE CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
517 CREEK RIDGE CT	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
709 N EDISON ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
705 N EDISON ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
701 N EDISON ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
404 FIRESTONE	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
412 FIRESTONE	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
416 FIRESTONE ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
420 FIRESTONE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
429 FIRESTONE	N	N	U	U	Construction Records	C	C	C		N/R	N			N	

405 FIRESTONE	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
612 FORD ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
621 FORD ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
2142 E ILLINOIS HWY 15	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
2134 E ILLINOIS HWY 15	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
2130 E ILLINOIS HWY 15	N	N	U	U	Visual Inspection/Survey Response	C	C	C		N/R	N			N	
3400 TWELVE OAKS LANE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1935 E ILLINOIS HWY 15	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
1885 E ILLINOIS HWY 15	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
2219 E ILLINOIS HWY 15	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
7723 JEFFERSON RD	N	N	U	U	Visual Inspection/Survey Response	C	C	C		N/R	N			N	
7729 JEFFERSON RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
405 S STATE ST	Y	N	U	U	Survey Response	C	C	C		N/R	N			N	
550 W PHILLIPS ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
801 N STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
2 COMMERCE DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
6 COMMERCE DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
1201 ANISE CT	N	N	U	U	Visual Inspection/Survey Response	C	C	C		N/R	N			N	
901 WINGMEAD DR	N	N	U	U	Material Invoice/Visual Inspection	C	C	C		N/R	N			N	
5490 BARBER LANE	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
5498 BARBER LANE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
5491 BARBER LANE	N	N	U	U	Material Invoice/Survey Response	C	C	P		N/R	N			N	
5483 BARBER LANE	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
5469 BARBER LANE	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
5451 BARBER LANE	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
5440 BARBER LANE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
5512 BARBER LANE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
5456 BARBER LANE	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
5462 BARBER LANE	N	N	U	U	Material Invoice	C	C	C		N/R	N			N	
900 WINGMEAD DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
5467 OAK THORN DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
5459 OAK THORN DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
5451 OAK THORN DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
5443 OAK THORN DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
5435 OAK THORN DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
5427 OAK THORN DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
5426 OAK THORN DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
5434 OAK THORN DR	N	N	U	U	Material Invoice/Survey Response/Visual Inspection	C	C	C		N/R	N			N	
5444 OAK THORN DR	N	N	U	U	Material Invoice/Survey Response/Visual Inspection	C	C	C		N/R	N			N	
918 BAY POINTE DR	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
926 BAY POINTE DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
934 BAY POINTE DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
942 BAY POINTE DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
950 BAY POINTE DR	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
957 BAY POINTE DR	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
941 BAY POINTE DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
933 BAY POINTE DR	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	

925 BAY POINTE DR	N	N	U	U	Material Invoice/Survey Response/Visual Inspection	C	C	P		N/R	N			N
917 BAY POINTE DR	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N
5460 OAK THORN DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N
918 WINGMEAD DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N
924 WINGMEAD DR	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N
925 WINGMEAD DR	N	N	U	U	Material Invoice/Survey Response	C	C	P		N/R	N			N
917 WINGMEAD DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
924 PROMONTORY PINES	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N
932 PROMONTORY PINES	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N
964 PROMONTORY PINES	N	N	U	U	Material Invoice/Survey Response	C	C	C		N/R	N			N
972 PROMONTORY PINES	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
980 PROMONTORY PINES	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
955 PROMONTORY PINES	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N
947 PROMONTORY PINES	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
931 PROMONTORY PINES	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
923 PROMONTORY PINES	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N
903 PROMONTORY PINES	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N
1017 TORRINGTON LN	N	N	U	U	Material Invoice/Survey Response	C	C	C		N/R	N			N
1013 TORRINGTON LN	N	N	U	U	Survey Response/Material Invoice	C	C	P		N/R	N			N
1009 TORRINGTON LN	N	N	U	U	Construction Records	C	C	C		N/R	N			N
1005 TORRINGTON LN	N	N	U	U	Construction Records	C	C	C		N/R	N			N
1001 TORRINGTON LN	N	N	U	U	Survey Response	C	C	C		N/R	N			N
300 CHIMNEY ROCK DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N
308 CHIMNEY ROCK DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N
312 CHIMNEY ROCK DR	N	N	U	U	Construction Records	C	C	P		N/R	N			N
316 CHIMNEY ROCK DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N
320 CHIMNEY ROCK DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N
324 CHIMNEY ROCK DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N
404 CHIMNEY ROCK DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N
408 CHIMNEY ROCK DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N
328 CHIMNEY ROCK DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N
332 CHIMNEY ROCK DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N
315 CHIMNEY ROCK DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N
409 CHIMNEY ROCK DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N
401 CHIMNEY ROCK	N	N	U	U	Construction Records	C	C	C		N/R	N			N
335 CHIMNEY ROCK DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N
331 CHIMNEY ROCK DR	N	N	U	U	Material Invoice	C	C	C		N/R	N			N
327 CHIMNEY ROCK DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N
321 CHIMNEY ROCK DR	N	N	U	U	Material Invoice/Survey Response	C	C	C		N/R	N			N
1000 TORRINGTON LN	N	Y	U	U	Construction Records/Survey Response	C	C	P		N/R	N			N
309 CHIMNEY ROCK	N	N	U	U	Survey Response	C	C	P		N/R	N			N
1004 TORRINGTON LN	N	N	U	U	Construction Records	C	C	C		N/R	N			N
304 GLENROCK LN	N	N	U	U	Survey Response	C	C	C		N/R	N			N
308 GLENROCK LN	N	N	U	U	Construction Records	C	C	C		N/R	N			N
312 GLENROCK LN	N	N	U	U	Survey Response	C	C	C		N/R	N			N
316 GLENROCK LN	N	N	U	U	Construction Records	C	C	C		N/R	N			N
320 GLENROCK LN	N	N	U	U	Construction Records	C	C	C		N/R	N			N
324 GLENROCK LN	N	N	U	U	Construction Records	C	C	C		N/R	N			N
328 GLENROCK LN	N	N	U	U	Survey Response/Material Invoice	C	C	C		N/R	N			N

333 GLENROCK LN	N	N	U	U	Construction Records	C	C	P		N/R	N			N	
329 GLENROCK LN	N	N	U	U	Material Invoice	C	C	C		N/R	N			N	
325 GLENROCK LN	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
321 GLENROCK LN	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
317 GLENROCK LN	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
313 GLENROCK LN	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
309 GLENROCK LN	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
305 GLENROCK LN	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
1012 TORRINGTON LN	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
304 SLEEPING INDIAN	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
308 SLEEPING INDIAN DR	N	N	U	U	Construction Records	C	C	P		N/R	N			N	
312 SLEEPING INDIAN DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
324 SLEEPING INDIAN DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
328 SLEEPING INDIAN DR	N	N	U	U	Material Invoice/Survey Response	C	C	C		N/R	N			N	
332 SLEEPING INDIAN DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
340 SLEEPING INDIAN DR	N	N	U	U	Material Invoice	C	C	C		N/R	N			N	
354 SLEEPING INDIAN DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
358 SLEEPING INDIAN DR	N	N	U	U	Material Invoice/Survey Response	C	C	C		N/R	N			N	
362 SLEEPING INDIAN DR	N	N	U	U	Material Invoice	C	C	C		N/R	N			N	
366 SLEEPING INDIAN DR	N	N	U	U	Material Invoice	C	C	C		N/R	N			N	
371 SLEEPING INDIAN DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
343 SLEEPING INDIAN DR	N	N	U	U	Survey Response/Material Invoice	C	C	C		N/R	N			N	
325 SLEEPING INDIAN DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
321 SLEEPING INDIAN DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
309 SLEEPING INDIAN DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
313 TORRINGTON LN	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
304 TORRINGTON LN	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
308 TORRINGTON LN	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
312 TORRINGTON LN	N	N	U	U	Material Invoice	C	C	C		N/R	N			N	
316 TORRINGTON LN	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
320 TORRINGTON LN	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
317 TORRINGTON LN	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
309 TORRINGTON LN	N	N	U	U	Survey Response/Material Invoice	C	C	C		N/R	N			N	
201 SLEEPING INDIAN DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
300 SILVERTHORNE DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
304 SILVERTHORNE DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
308 SILVERTHORNE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
312 SILVERTHORNE DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
316 SILVERTHORNE DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
320 SILVERTHORNE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
324 SILVERTHORNE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
336 SILVERTHORNE DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
400 SILVERTHORNE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
408 SILVERTHORNE	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
412 SILVERTHORNE DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
416 SILVERTHORNE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
420 SILVERTHORNE DR	N	N	U	U	Construction Records	C	C	P		N/R	N			N	
419 SILVERTHORNE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
403 SILVERTHORNE DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
400 TELLURIDE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
404 SILVERTHORNE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
407 SILVERTHORNE DR	N	N	U	U	Material Invoice	C	C	C		N/R	N			N	
415 SILVERTHORNE DR	N	N	U	U	Material Invoice/Survey Response	C	C	P		N/R	N			N	

409 TELLURIDE DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
405 TELLURIDE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
413 TELLURIDE DR	N	N	U	U	Construction Records	C	C	P		N/R	N			N	
417 TELLURIDE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
412 TELLURIDE DR	N	N	U	U	Survey Response/Material Invoice	C	C	C		N/R	N			N	
401 TELLURIDE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
408 TELLURIDE DR	N	N	U	U	Construction Records	C	C	P		N/R	N			N	
404 TELLURIDE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
313 TELLURIDE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
309 TELLURIDE DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
301 TELLURIDE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
300 TELLURIDE DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
304 TELLURIDE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
308 TELLURIDE DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
312 TELLURIDE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
337 SILVERTHORNE DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
333 SILVERTHORNE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
325 SILVERTHORNE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
321 SILVERTHORNE DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
317 SILVERTHORNE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
313 SILVERTHORNE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
309 SILVERTHORNE DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
305 SILVERTHORNE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
301 SILVERTHORNE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
224 ALAMOSA DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
222 ALAMOSA DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
228 ALAMOSA DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
226 ALAMOSA DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
209 ALAMOSA DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
225 ALAMOSA DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
211 ALAMOSA DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
213 ALAMOSA DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
215 ALAMOSA DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
217 ALAMOSA DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
219 ALAMOSA DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
221 ALAMOSA DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
223 ALAMOSA DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
227 ALAMOSA DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
229 ALAMOSA DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
231 ALAMOSA DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
233 ALAMOSA DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
235 ALAMOSA DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
205 ALAMOSA DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
207 ALAMOSA DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
201 ALAMOSA DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
203 ALAMOSA DR	N	N	U	U	Construction Records	C	C	P		N/R	N			N	
200 ALAMOSA DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
202 ALAMOSA DR	N	N	U	U	Construction Records/Survey Response	C	C	C		N/R	N			N	
204 ALAMOSA DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
206 ALAMOSA DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
205 SILVERTHORNE DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
207 SILVERTHORNE DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
201 SILVERTHORNE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
203 SILVERTHORNE DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	

218 ALAMOSA DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
220 ALAMOSA DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
328 SILVERTHORNE DR	N	N	U	U	Material Invoice	C	C	C		N/R	N			N	
329 SILVERTHORNE DR	N	N	U	U	Material Invoice	C	C	C		N/R	N			N	
553 CEMETERY ROAD	N	N	U	U	Material Invoice/Survey Response	C	C	C		N/R	N			N	
305 TORRINGTON LN	N	N	U	U	Material Invoice	C	C	C		N/R	N			N	
316 SLEEPING INDIAN DR	N	N	U	U	Material Invoice	C	C	C		N/R	N			N	
3709 STATE ROUTE 15	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
3713 STATE ROUTE 15	N	N	U	U	Material Invoice	C	C	C		N/R	N			N	
416 TELLURIDE DR	N	N	U	U	Material Invoice	C	C	P		N/R	N			N	
506 DRACO DR	N	N	U	U	Material Invoice	C	C	C		N/R	N			N	
504 DRACO DR	N	N	U	U	Material Invoice	C	C	C		N/R	N			N	
305 SLEEPING INDIAN DR	N	N	U	U	Material Invoice	C	C	C		N/R	N			N	
332 SILVERTHORNE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
301 TORRINGTON	N	N	U	U	Material Invoice	C	C	C		N/R	N			N	
1 CHERRY TREE LN	N	N	U	U	Material Invoice	C	C	C		N/R	N			N	
313 SLEEPING INDIAN DR	N	N	U	U	Material Invoice	C	C	C		N/R	N			N	
3719 STATE ROUTE 15	N	N	U	U	Survey Response/Material Invoice	C	C	C		N/R	N			N	
210 ALAMOSA DR	N	N	U	U	Material Invoice/Survey Response	C	C	C		N/R	N			N	
212 ALAMOSA DR	N	N	U	U	Material Invoice/Survey Response	C	C	C		N/R	N			N	
7632 JEFFERSON RD	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
7716 JEFFERSON RD	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
7730 JEFFERSON RD	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
7736 JEFFERSON RD	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
7718 JEFFERSON RD	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
7708 KAMPER COTTAGE LANE	N	N	U	U	Material Invoice	C	C	C		N/R	N			N	
7709 KAMPER COTTAGE LANE	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
3042 SAVE RD	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
3122 SAVE ROAD	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
3001 SAVE RD	N	N	U	U	Construction Records	C	C	P		N/R	N			N	
3121 SAVE ROAD	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
320 SLEEPING INDIAN DR	N	N	U	U	Material Invoice	C	C	C		N/R	N			N	
3731 STATE ROUTE 15	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
3831 STATE ROUTE 15	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
3837 STATE ROUTE 15	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
400 CHIMNEY ROCK DR	N	N	U	U	Material Invoice	C	C	P		N/R	N			N	
3901 STATE ROUTE 15	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
3921 STATE ROUTE 15	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
214 ALAMOSA DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
216 ALAMOSA DR	N	N	U	U	Material Invoice/Survey Response	C	C	C		N/R	N			N	
3714 STATE ROUTE 15	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
520 URBANNA DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
3646 STATE ROUTE 15	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
3726 STATE ROUTE 15	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
3725 STATE ROUTE 15	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
3735 STATE ROUTE 15	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
7831 JEFFERSON RD	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
3746 STATE ROUTE 15	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
3750 STATE ROUTE 15	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
3756 STATE ROUTE 15	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
3806 STATE ROUTE 15	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
3812 STATE ROUTE 15	N	N	U	U	Survey Response	C	C	C		N/R	N			N	

7843 JEFFERSON RD	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
367 SLEEPING INDIAN DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
3824 STATE ROUTE 15	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
300 SLEEPING INDIAN DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
3818 STATE ROUTE 15	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
401 FOXTAIL DR	N	N	U	U	Visual Inspection	P	P	P		N/R	N			N	
405 FOXTAIL DR	N	N	U	U	Visual Inspection	P	P	P		N/R	N			N	
409 FOXTAIL DR	N	N	U	U	Visual Inspection	P	P	P		N/R	N			N	
417 FOXTAIL DR	N	N	U	U	Visual Inspection	P	P	P		N/R	N			N	
421 FOXTAIL DR	N	N	U	U	Visual Inspection	P	P	P		N/R	N			N	
429 FOXTAIL DRIVE	N	N	U	U	Logbook/Visual Inspection/Survey Response	P	P	P		N/R	N			N	
437 FOXTAIL DR	N	N	U	U	Visual Inspection	P	P	P		N/R	N			N	
441 FOXTAIL DR	N	N	2021	2021	Logbook/Visual Inspection/Survey Response	P	P	P		N/R	N			N	
445 FOXTAIL DR	N	N	U	U	Visual Inspection	P	P	P		N/R	N			N	
444 FOXTAIL DR	N	N	4/8/2021	2021	Logbook/Visual Inspection	C	C	P		N/R	N			N	
436 FOXTAIL DR	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
424 FOXTAIL DR	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
420 FOXTAIL DR	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
416 FOXTAIL DR	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
408 FOXTAIL DR	N	N	U	U	Visual Inspection	P	P	P		N/R	N			N	
400 FOXTAIL DR	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
1013 Torrey Lane	N	N	2021	2021	Logbook/Visual Inspection	P	P	P		N/R	N			N	
1009 TORREY LANE	N	N	2021	2021	Logbook/Visual Inspection	P	P	P		N/R	N			N	
1005 TORREY LANE	N	N	4/9/2021	2021	Survey Response/Logbook/Visual Inspection	P	P	P		N/R	N			N	
1004 TORREY LANE	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
711 W APPLE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
727 W APPLE ST	N	N	U	U	Visual Inspection	C	C	GRR	Y	N/R	N			N	
906 W APPLE ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
810 W APPLE ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
806 W APPLE ST	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
7 CHERRY TREE LN	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
712 W APPLE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
10 CHERRY TREE LN	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
709 KESSLER RD	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
705 KESSLER RD	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
815 KESSLER RD	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
903 WOLF RD	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
501 N MAIN ST	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
406 FIRST ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
371 URBANNA DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
150 WILD CHERRY LANE	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
125 SUNRISE DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
170 SUNRISE DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
113 SUNRISE DR	N	N	U	U	Visual Inspection/Survey Response	C	C	C		N/R	N			N	
616 OLD FAYETTEVILLE	N	N	U	U		C	C	C		N/R	N			N	
621 OLD FAYETTEVILLE RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
629 OLD FAYETTEVILLE RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
701 JACOBS LANE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
641 OLD FAYETTEVILLE RD	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
624 OLD FAYETTEVILLE	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
632 OLD FAYETTEVILLE RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	

731 SHADY LANE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
732 SHADY LANE	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
744 SHADY LANE	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
712 SHADY LANE	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
801 OLD FAYETTEVILLE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
809 OLD FAYETTEVILLE	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
821 OLD FAYETTEVILLE	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
829 OLD FAYETTEVILLE	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
900 OLD FAYETTEVILLE RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
912 OLD FAYETTEVILLE RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
914 OLD FAYETTEVILLE RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
916 OLD FAYETTEVILLE RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
915 OLD FAYETTEVILLE RD	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
926 OLD FAYETTEVILLE RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
927 OLD FAYETTEVILLE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
945 OLD FAYETTEVILLE RD	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
3904 STATE ROUTE 15	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
3922 STATE ROUTE 15	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
3910 STATE ROUTE 15	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
3926 STATE ROUTE 15	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
3858 STATE ROUTE 15	N	N	U	U	Construction Records	C	C	P		N/R	N			N	
3834 STATE ROUTE 15	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
3830 STATE ROUTE 15	N	N	U	U	Construction Records	C	C	P		N/R	N			N	
3815 STATE ROUTE 15	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
3761 STATE ROUTE 15	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
3857 STATE ROUTE 15	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
3745 STATE ROUTE 15	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
3744 STATE ROUTE 15	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
3738 STATE ROUTE 15	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
3732 STATE ROUTE 15	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
3720 STATE ROUTE 15	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
3703 STATE ROUTE 15	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
3640 STATE ROUTE 15	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
3641 STATE ROUTE 15	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
3619 STATE ROUTE 15	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
3623 STATE ROUTE 15	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
733 URBANNA DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
599 URBANNA DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
550 URBANNA DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
767 CEMETERY ROAD	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
769 CEMETERY ROAD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
710 CEMETERY ROAD	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
716 CEMETERY ROAD	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
740 CEMETERY ROAD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
750 CEMETERY ROAD	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
771 CEMETERY ROAD	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
811 CEMETERY ROAD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
815 CEMETERY ROAD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
819 CEMETERY ROAD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
820 CEMETERY ROAD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
821 CEMETERY ROAD	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
833 CEMETERY ROAD	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
90 PRESTON DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
30 PRESTON DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
873 CEMETERY ROAD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	

889 CEMETERY RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
901 CEMETERY RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
97 BARBER LANE	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
5520 BARBER LANE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
120 BARBER LANE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
5733 BARBER LANE	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
155 BARBER LANE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
970 CEMETERY ROAD	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
967 CEMETERY ROAD	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
5765 BARBER LANE	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
5913 BARBER LANE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
5807 BARBER LANE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8330 JACKS RUN RD	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
5855 BARBER LANE	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
8362 WOODLAND PATH	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
8367 WOODLAND PATH	N	Y	U	U	Visual Inspection/Survey Response	C	C	P		N/R	N			N	
8343 WOODLAND PATH	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8300 WOODLAND PATH	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8338 WOODLAND PATH	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8331 WOODLAND PATH	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
8315 WOODLAND PATH	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
5909 BARBER LANE	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
8342 JACKS RUN RD	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
5930 MOON LANE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
5901 MOON LANE	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
BARBER LANE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8262 JACKS RUN RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8312 JACKS RUN RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8324 JACKS RUN RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8443 RIVER KING DR TRAILR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8380 PEABODY RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8451 RIVER KING DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8114 PEABODY RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8115 PEABODY RD	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
8123 PEABODY RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8131 PEABODY RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8139 PEABODY RD	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
8201 PEABODY RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8209 PEABODY RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8217 PEABODY RD	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
8225 PEABODY RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8233 PEABODY RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8241 PEABODY RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8301 PEABODY RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8309 PEABODY RD	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
8317 PEABODY RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8325 PEABODY RD	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
8326 HERON COVE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8318 HERON COVE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	

8310 HERON COVE	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
8302 HERON COVE	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
8311 HERON COVE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8323 HERON COVE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8403 HERON COVE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8410 HERON COVE	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
8402 HERON COVE	N	N	U	U	Visual Inspection/Survey Response	C	C	C		N/R	N			N	
8403 RIVER KING DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8411 RIVER KING DR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8419 RIVER KING DR	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
8427 RIVER KING DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
8435 River King Drive	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8324 PEABODY RD	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
8316 PEABODY RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8306 PEABODY RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8238 PEABODY RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8230 PEABODY RD	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
8216 PEABODY RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8204 PEABODY RD	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
8122 PEABODY RD	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
8435 RIVER KING DR	N	N	U	U	Material Invoice/Survey Response	C	C	C		N/R	N			N	
8105 PEABODY RD	N	N	U	U	Material Invoice/Visual Inspection	C	C	C		N/R	N			N	
361 TOWN & COUNTRY	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
500 N STATE ST	Y	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
701 S STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
800 S STATE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
820 S STATE ST	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
409 W APPLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
408 S BELLEVILLE	Y	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
408 S BELLEVILLE	Y	N	U	U	Survey Response/Visual Inspection	O	O	O		N/R	N			N	
408 S BELLEVILLE ST	Y	N	U	U	Survey Response/Visual Inspection	O	O	O		N/R	N			N	
408 S BELLEVILLE	Y	N	U	U		C	C	C		N/R	N			N	
401 S MONROE ST	Y	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
401 S MONROE ST	Y	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
SOFTBALL/BASEBALL DIAMOND	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
CONCESSION STAND	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
401 S MONROE	Y	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
804 N STATE ST	Y	N	U	U	Survey Response	C	C	C		N/R	N			N	
804 N STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
21 SOUTHGATE DR	N	N	U	U	Survey Response	C	C	P		N/R	N			N	
108 S STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
102 N ALTON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
715 N STATE ST	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
408 S BELLEVILLE ST	Y	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
202 S STATE	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
202 S STATE	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
210 W WHITE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
311 S STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1799 N STATE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	

707 N STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
7 N BELLEVILLE ST	Y	N	U	U	Survey Response	C	C	C		N/R	N			N	
9 N ALTON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
6 N ALTON ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
2 N ALTON ST	Y	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
410 W WASHINGTON ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
900 N STATE ST	Y	N	U	U	Survey Response	C	C	P		N/R	N			N	
11 SOUTHGATE CENTER	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
14 SOUTHGATE CENTER	Y	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
750 S STATE	Y	N	U	U	Survey Response/Visual Inspection	O	O	O		N/R	N			N	
416 S RICHLAND ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
502 S RICHLAND BLDG 1A	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
502 S RICHLAND BLDG 2	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
3 S BELLEVILLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
501 W APPLE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
5516 WILLOW SPRINGS LN	N	N	U	U	Visual Inspection	P	P	C		N/R	N			N	
5 W APPLE ST	Y	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
751 S STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
708 N STATE ST	Y	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
708 N STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
800 N STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
407 S BELLEVILLE ST	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
301 S STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
860 S STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1231 N STATE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
5 COMMERCE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
10 COMMERCE DR	N	N	U	U	Survey Response	C	C	C		N/R	N			N	
9 INDUSTRIAL DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
1210 N STATE	N	N	U	U	Visual Inspection	P	P	C		N/R	N			N	
1414 SOUTH STATE ST	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
2 INDUSTRIAL DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
4 INDUSTRIAL DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
8 INDUSTRIAL DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
5 INDUSTRIAL DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
425 MARKET PLACE DR	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
BLDG #5 MARKET PLACE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
1216 W APPLE	N	N	U	U	Material Invoice/Survey Response/Visual Inspection	C	C	C		N/R	N			N	
401 MARKET PLACE	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
7470 POWER PLANT LN	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
251 MARKET PLACE	N	N	U	U	Survey Response/Visual Inspection	C	C	P		N/R	N			N	
BLDG #1 MARKET PLACE	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
341 MARKET PLACE	N	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
353 MARKET PLACE	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
369 MARKET PLACE	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
605 N STATE ST	Y	N	U	U	Survey Response/Visual Inspection	P	P	P		N/R	N			N	
13 COMMERCE DR	N	N	U	U	Material Invoice	C	C	C		N/R	N			N	
302 W WHITE ST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
10 SOUTHGATE CENTER	N	N	U	U	Material Invoice	C	C	C		N/R	N			N	
1 SOUTHGATE	Y	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
490 URBANNA DR	Y	N	U	U	Survey Response/Visual Inspection	C	C	C		N/R	N			N	
491 MARKET PLACE DR	N	N	U	U	Construction Records	C	C	C		N/R	N			N	

491 MARKET PL	N	N	U	U	Construction Records	C	C	C		N/R	N			N	
BRIARWOOD EAST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
BRIARWOOD WEST	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
CARDINAL CT MM	N	N	U	U	Visual Inspection	P	P	P		N/R	N			N	
DEERFIELD COURT	N	N	U	U	Visual Inspection	O	O	O		N/R	N			N	
Harris Court MM	N	N	U	U	Visual Inspection	C	C	P		N/R	N			N	
PARRISH MHP	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
PALOMAR	N	N	U	U	Visual Inspection	C	C	C		N/R	N			N	
1013 Torrey Lane	N	N	U	U	Visual Inspection	P	P	P		N/R	N			N	
106 S Edison	N	Y	U	U	Visual Inspection	C	C	C		N/R	N			N	
428 Foxtail Drive	N	N	U	U	Visual Inspection	P	P	P		N/R	N			N	
347 Sleeping Indian Dr	N	Y	U	2024	Visual Inspection/Construction Records/Material Invoice	C	C	P		N/R	N			N	
713 N Edison St	N	Y	2024	2024	Visual Inspection/Construction Records/Material Invoice	P	P	P		N/R	N			N	
717 N Edison St	N	Y	2024	2024	Visual Inspection/Construction Records/Material Invoice	P	P	P		N/R	N			N	
721 N Edison St	N	Y	2024	2024	Visual Inspection/Construction Records/Material Invoice	P	P	P		N/R	N			N	
1375 S State St	N	Y	2024	2024	Visual Inspection/Construction Records/Material Invoice	P	P	P		N/R	N			N	
971 Promitory Pines	N	Y	2024	2024	Visual Inspection/Construction Records/Material Invoice	P	P	P		N/R	N			N	
617 Ford St	N	Y	2024	2024	Visual Inspection/Construction Records/Material Invoice	P	P	P		N/R	N			N	
613 Ford St	N	Y	2024	2024	Visual Inspection/Construction Records/Material Invoice	P	P	P		N/R	N			N	
410 W High	N	N	U	U	Survey Response	C	C	C		N/R	N			N	